

Subdivisions of T. 32 S., R. 6 W.

CHAINS

77.30 Intersect North Boundary of Township at the cor. to secs. 1, 2, 35 and 36, which is a post 4 ins. sq., firmly set in the ground and marked, T 31 S R 6 W S 36 on NE. T 32 S R 6 W S 1 on SE. S 2 on SW. and S 35 on NW faces with 1 notch on East and 5 notches on West edges from which

A Fir, 8 ins. diam., bears N.28\*E., 6 lks. dist., marked T 31 S R 6 W S 36 B T.

A Fir, 6 ins. diam., bears S.53\*E., 50 lks. dist., marked T 32 S R 6 W S 1 B T.

A Fir, 18 ins. diam., bears S.60\*W., 47 lks. dist., marked T 32 S R 6 W S 2 B T.

A Fir, 14 ins. diam., bears N.30\*W., 59 lks. dist., marked T 31 S R 6 W S 35 B T.

Thence South on true line between Secs. 1 and 2.

Va. 18\*30'E

37.30 Set a Fir, post 3 ft. long 3 ins. sq., 24 ins. in the ground, for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  S. on W. face, from which

A Fir, 30 ins. diam., bears N.30\*E., 5 lks. dist., marked  $\frac{1}{4}$  S B T.

A Fir, 16 ins. diam., bears West 11 lks., marked  $\frac{1}{4}$  S B T.

77.30 The cor. to Secs. 1, 2, 11 and 12.

Land, mountainous.

Soil, 3rd. rate.

Timber, Fir, Pine, Cedar, Laurel and Chinquapin.

Undergrowth, same.

November 12, 1881.

The post cor. to secs. 22, 23, 26 and 27, being destroyed

I re-established same as per notes furnished. Bearing trees still standing, viz;

Set a Fir, post 4 ft. long, 4 ins. sq., 24 ins. in the ground, for the cor., marked T 32 S R 6 W S 23 on NE.