

Subdivisions of Tp. 32 S., R 7 W.

CHAINS	
	<p>North between Secs. 29 and 30</p> <p style="text-align: right;">Va.18*15'E.</p>
10.50	Creek, 1 lk wide course W
40.00	Set A Laurel post, 4 feet long 4 ins. sq., 24 ins. in the ground, marked $\frac{1}{4}$ S on W side for the $\frac{1}{4}$ Sec. Cor. from which;
	<p>A Fir, 60 ins. diam., bears S.40*E., 17 lks. marked $\frac{1}{4}$ S B T.</p> <p>A Laurel, 5 ins. diam., bears S.53*W., 36 lks. marked $\frac{1}{4}$ S B T.</p>
80.00	Set A Laurel post, 4 feet long 4 ins. sq., 18 ins. in the ground, for the corner to secs. 19, 20, 29 and 30 marked T 32 S R 7 W S 20 on NE; S 29 SE; S 30 SW and S 19 on the NW faces, also two notches on S and 5 on E angles of same, from which;
	<p>A Fir, 36 ins. diam., bears N.55*E., 70 lks. dist. marked T 32 S R 7 W S 20 B T.</p> <p>A Laurel, 16 ins. diam., bears S.15*E., 58 lks. dist. marked T 32 S R 7 W S 29 B T.</p> <p>A Laurel, 14 ins. diam., bears S.55*W., 38 lks. dist. marked T 32 S R 7 W S 30 B T.</p> <p>A Cedar, 10 ins. diam., bears N.5*W., 29 lks. dist. marked T 32 S R 7 W S 19 B T.</p>
	<p>Land, along W side of mountain spur.</p> <p>Soil, 4th rate.</p> <p>Timber, poor Fir, Cedar, Pine and Laurel.</p> <p>Undergrowth very dense same Balm, Live Oak and "Manzanita"</p>
	<p>East on Random line between Secs. 20 and 29</p> <p style="text-align: right;">Va.19'E.</p>
40.00	Set temporary $\frac{1}{4}$ Sec. Cor.
55.00	Steep rocky canyon course NW
63.00	Cow Creek, 200 lks. wide course NW Nov.6th 1881.
70.00	E side of rocky canyon course NW
78.00	Trail course NW
80.10	Intersect Sec. line 14 lks. N of Cor. to Secs. 20, 21, 28 and 29
	Thence I run
	N.89*54'W on true line between Secs. 20 and 29
	Va.same.
40.05	Set A Laurel post, 4 feet long 4 ins. sq., 24 ins. in the ground, marked $\frac{1}{4}$ on N S for the $\frac{1}{4}$ Sec. Cor. from which;
	<p>A Laurel, 6 ins. diam., bears S.88*W., 11 lks. marked $\frac{1}{4}$ S B T.</p> <p>A Laurel, 8 ins. diam., bears N.35*W., 39 lks. marked $\frac{1}{4}$ S B T.</p>
80.10	To Corner to Secs. 19, 20, 29 and 30
	<p>Land, broken and hilly.</p> <p>Soil, rocky 4th rate.</p> <p>Timber, chiefly Fir, Pine, Cedar, Laurel and Chinquapin.</p> <p>Underbrush same, Live Oak and Balm.</p>
	<p>West on Random line between Secs. 19 and 30</p> <p style="text-align: right;">Va.19'E.</p>
1.75	Creek, 2 lks. wide course N.
15.00	Top of Spur course N Begin steep descent.
26.50	Creek, 3 lks. wide course N Begin steep ascent.
40.00	Set temporary $\frac{1}{4}$ Sec. Cor.
42.00	Top of high Spur course N Begin descent.
61.50	Water Ditch course NE.
67.00	Creek, 40 lks. course N.20*E., Begin ascent.
81.10	Intersect W boundary of Township 16 lks. N of Cor. to