

Resurvey East Bdy., T. 32., R. 9 W.

CHAINS

marked $\frac{1}{4}$ S 24 B T.

- 46.00 Top of spur, slopes SE.; descend NE slope.
- 47.65 Dry ravine, course E.; ascend steep slope.
- 61.85 Top of spur, slopes NE.; descend.
- 67.35 Creek, 5 lks. wide, course SE.; ascend steep slope.
- 72.16 Intersect the old cor. of secs. 13, 18, 19 and 24, which is

a decayed and partly burned post, witnessed as described by the surveyor general. I change this cor. to refer to secs. 18 and 19 only and perpetuate it as follows: alongside the old cor.

Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for cor. of secs. 18 and 19, T. 32 S., R. 8 W. only, with brass cap marked

T32S
S18
S19
R8W

1917

from which

A Fir, 5 ins. diam., bears N.54*E., 75 lks. dist., marked T 32 S R 8 W S 18 B T (New B.T.)

A Fir, 18 ins. diam., bears S.55*E., 115 lks. dist., marked T 32 S R 8 W S 19 B T (Old B.T.)

Thence

N.0*26'W., continuing my measurements

- 76.85 Top of spur, slopes SE.; descend.
- 80.00 Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for cor. of secs. 13 and 24, with brass cap marked

T32S
S13
S24
R9W

1917

from which

A Fir, 18 ins. diam., bears S.51*W., 91 lks. dist. marked T 32 S R 9 W S 24 B T.