

County Surveyor's Record, Douglas County, Oregon

21

Subdivisions of T. 33 S. R. 5 W.

WEST COAST PRINTING & BINDING CO. PORTLAND, 18735

CHAINS		
	North 2'W bet. secs. 2 and 3.	
	Va 19*E.	
	Descend on NE slope.	
7.90	Ravine 20 ft. deep and spring branch 1 lk. wide, course NE.	
9.00	Ravine 20 ft. deep and spring branch 1 lk. wide, course NE.	
10.95	Foot of descent -200 ft. and branch 3 lks. wide, course E. Ascend on S slope.	
16.70	Top of mt. spur and ascent bears E.	+200
	Descend on NE slope.	
17.80	A Fir, 24 ins. diam. line tree marked with two notches on N and S sides.	
21.75	S edges of small swamp.	
23.50	Foot of descent and ascend on S slope.	-100
24.50	Leave swamp.	
30.55	A Fir, 12 ins. diam. line tree, marked with two notches on N and S sides.	
38.30	S pine, 60 ins. diam. line tree marked with two notches on N and S sides.	
39.00	Top of ridge +600 bears N.30*E and S30*W. Descend on W slope.	
40.00	Set a slate stone 18 x 12 x 6 ins. 12 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on W face from which A Fir, 12 ins. diam., bears N.30*45'E., 149 lks. dist. marked $\frac{1}{4}$ S B T. A S. Pine, 30 ins. diam., bears S.36*30'W., 112 lks. dist. marked $\frac{1}{4}$ S B T.	
55.00	Begin to descend now on NE slope.	
60.60	A Fir, 24 ins. diam., line tree marked with 2 notches on N and S sides.	
62.50	Begin to descend now on N slope of mt. spur.	
66.50	Foot of descent -800 ft. and creek 5 lks. wide, course NE. Along creek bottom.	