

## County Surveyor's Record, Douglas County, Oregon

26

## Subdivisions of T. 33 S., R. 5 W.

CHAINS	North 2°W between secs. 15 and 16.	
	Va 19°E.	
	Ascend mountain on S slope.	
00.50	Leave timber and enter very dense brush of Hazel, Buckhorn, Manzanita, and live Oak.	
7.00	Top of ascent and Divide bears E and W.	+200
	Descend mountain on N slope.	
9.00	Enter heavy timber.	
32.10	Foot of descent -800 ft. and spring branch 2 lks. wide course, W. Ascend mountain S slope.	
32.15	A Fir, 36 ins. diam. line tree, marked with 2 notches on N and S sides.	
37.00	Cor. to miners deserted claim bears W. 10 lks.	
38.50	Top of mountain spur #200 ft. bears S.	
	Descend on NW slope.	
40.00	A Fir, 12 ins. diam. which I marked $\frac{1}{4}$ S on W side for $\frac{1}{4}$ sec. cor. from which	
	A Cedar, 6 ins. diam., bears N.76°E., 42 lks. dist. marked $\frac{1}{4}$ S B T.	
	A Fir, 8 ins. diam., bears S.58°W., 44 lks. dist. marked $\frac{1}{4}$ S B T.	
44.40	A Fir, 36 ins. diam., line tree, marked with two notches on N and S sides.	
45.17	Foot of descent -200 and spring branch 1 lk. wide, course W. Ascend steep S slope.	
58.40	Top of steep ascent and mt. spur, bears W and enter old burn. Along through burn and steep W slope.	+300
59.38	A post with notice of being the SE cor. "Poorman's Mine".	
68.85	Being to descend rapidly on the N slope.	
70.00	Leave burn.	
80;00	Set hard slate rock 16 x 12 x 8 ins. 11 ins. in the ground for cor. to secs. 9, 10, 15 and 16 marked with 4 notches on the S and 3 notches on the E edges from which	