

County Surveyor's Record, Douglas County, Oregon

South Boundary of T. 24 S., R 2 E.

CHAINS	
	West, bet. Secs. 4 and 33. Descend 620 ft. over NW slope, through heavy timber and dense undergrowth.
6.50	Dry ravine, course N.
14.10	Dry ravine, course NW; continue descent along broken N slope.
25.00	Continue descent over NW slope.
28.70	Brook, 1 lk. wide, course NW; ascend 235 ft. along N slope.
33.50	Continue ascent over NE slope.
37.30	Spur, slopes NW; descend 100 ft. over W slope.
40.00	Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ Sec. cor., with brass cap marked
	$\begin{array}{r} S33 \\ \frac{1}{4} \\ \hline S4 \\ 1926 \end{array}$
	from which
	A Fir, 30 ins. diam., bears N.21*E., 42 lks. dist., marked $\frac{1}{4}$ S 33 B T.
	A Fir, 30 ins. diam., bears S.68*E., 36 lks. dist., marked $\frac{1}{4}$ S 4 B T.
	Descend 815 ft. over SW slope.
41.80	Enter open meadow, bears NW and SW.
46.15	Leave open meadow, enter heavy timber and dense undergrowth, bears N and S.
50.00	Continue descent over W slope.
60.80	Steamboat Creek, 80 lks. wide, course SE; ascend 25 ft. to
62.20	Thence over flat.
72.50	Steamboat Trail, and Forest Service telephone line, bears N and S.
76.25	Leave flat, bears NE and SW; ascend 175 ft. over SE slope.
80.00	Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for cor. of Secs. 4, 5, 32 and 33, with brass cap marked