


County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 27 S., R. 1 E.

CHAINS	<p>From the cor. of secs. 19, 20, 29 and 30, as herein- before described.</p> <p>Thence,</p> <p>N.0*04'W., bet. secs. 19 and 20.</p> <p>Over mountainous land, through timber and brush.</p> <p>Ascend 169 ft. over SW. slope.</p> <p>7.13 Clover Creek Way Trail, bears SE. and NW.</p> <p>7.20 Ridge, bears E. and NW.</p> <p>Descend 567 ft. over broken NE. slope.</p> <p>21.64 Marsh, 1 ch. wide, drains NE.</p> <p>40.00 Set an iron post, 3 ft. long, 1 in. in dia., 87 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked.</p> <div style="text-align: center; margin: 10px 0;"> $\frac{1}{4}$  S19 S20 1927 </div> <p>from which,</p> <p>A hemlock, 20 ins. in dia., bears N.25*E., 84 lks. dist., marked $\frac{1}{4}$ S 20 B T</p> <p>A hemlock, 20 ins. in dia., bears N.56*W., 51 lks. dist., marked $\frac{1}{4}$ S 19 B T</p> <p>Descend 537 ft. over broken N. slope.</p> <p>48.60 Spring branch, 1 lk. wide, course NE.</p> <p>50.90 Creek, 5 lks. wide, course N.20*W.</p> <p>64.20 Same creek, course N. from the SW.</p> <p>70.20 Leave same creek, course N.10*E.</p> <p>77.10 Point of spur, slopes NE.</p> <p>80.00 Set an iron post, 3 ft. long, 2 ins. in dia., 27 ins. in the ground, for the cor. of secs. 17, 18, 19 and 20, with brass cap marked.</p> <div style="text-align: center; margin: 10px 0;"> T27SR1E S18 S17 S19 S20 1927 </div> <p>from which,</p> <p>A cedar, 16 ins. in dia., bears N.28*E., 61 lks. dist., marked T 27 S R 1 E S 17 B T</p>
--------	---