

Subdivisions, T. 31 S., R. 2 E.

CHAINS

marked T 31 S R 2 E S 23 B T.

Land, broken and mountainous.

Soil, good.

Timber, Fir and Pine.

Undergrowth, Vine Maple.

Heavily timbered and mountainous.

80.00 chs.
Sept. 13, 1891.

S.89*37'E., on a random line bet. secs. 24 and 25.
Var.19*E.

40.00 Set temporary 1/4 sec. cor.

79.70 Intersect the East bdy. of the Tp. 23 lks. South of
the cor. to secs. 19, 24, 25 and 30.

Thence I run

N.89*47'W., on a true line bet. secs. 24 and 25
Var.19*E.

Through heavy Fir and Pine timber.

10.15 A branch, 5 lks. wide, course N.80*E.

39.85 Set a stone, 14x12x8 ins. 9 ins. in the ground, for
1/4 sec. cor. marked 1/2 on N. face, from which
A White Fir, 5 ins. diam., bears S.85*W., 8 lks.
marked 1/2 S B T.
A Cedar, 10 ins. diam., bears N.13*E., 23 lks.
marked 1/2 S B T.

64.00 A branch, 5 lks. wide, course N.80*E.

79.70 The cor. to secs. 23, 24, 25 and 26.

Land, rolling and mountainous.

Soil, 1st rate.

Timber, Fir and Pine.

Undergrowth, Vine Maple and Lilac.

Heavily timbered and mountainous.

79.70 chs.
Sept. 14, 1891.