

CHAINS

Smith River Route,
Reedsport, Oregon
October 12, 1951

In 1905, at my father's request, I drove an iron tipped pitchfork handle in the ground alongside an old line fence on the right bank of Smith River, on the line between secs. 28 and 33, in T. 20 S., R. 10 W., of the Willamette Meridian, in order to preserve the identity of the section line when the fence was removed. At that time the location of both the section line and the cor. of secs. 27, 28, 33 and 34, was known and accepted from the evidence of the original survey which is now gone. The pitchfork handle still occupies the same position and was shown by me to Thomas A. Tillman, Cadastral Engineer, in June, 1951.

(Signed) Ray M. Dailey