

County Surveyor's Record, Douglas County, Oregon

T. 25 S., R. 2 W.

CHAINS

The entire area is drained by Rock Creek, from one to two chains in width, and its smaller tributary, Harrington Creek. Several beautiful waterfalls are located in branches of Harrington Creek near the line between Sections 5 and 6.

Except for several disused trails the main access in the resurveyed area is a gravelled logging road along Rock Creek. Much of the area is difficult to reach at present, but logging operations will soon cause roads to reach nearly every part.

There are no settlers in the area surveyed. No indication of mineral was noted.

The average of many readings over all parts of the resurveyed portion gives a value of $21^{\circ} 38'$ E., for the mean magnetic declination. The range is about 13° , and the magnetic compass is useless except for the roughest orientation.