

County Surveyor's Record, Douglas County, Oregon

T. 24 S., R. 7 W.

CHAINS

The following record represents a correction of the dependent resurvey of a portion of the east boundary of township 24 south, range 7 west, and a portion of the south boundary of township 23 south, range 7 west, Willamette Meridian, Oregon, as executed by Orville N. Eggen, in 1957, under Group No. 244.

T. 23 S., R. 6 W., was resurveyed by Otis O. Gould, Joseph S. Gawron, and Orville N. Eggen in the period from 1943 to 1957. Additional resurvey was necessary in T. 24 S., R. 7 W., to obtain control for the restoration of lost corners. The notes were approved and the plat accepted August 24, 1960. In February, 1964, it was reported that two original corners had been recovered on the W. bdy. of T. 23 S., R. 6 W., and had not been used by Eggen during his resurvey. An investigation disclosed evidence of original corners, the recovery of which affects the control used by Eggen for the proportionate restoration of lost corners along the E. bdy. of T. 24 S., R. 7 W., and the S. bdy. of T. 23 S., R. 7 W.

The method of procedure of this correction of resurvey is as described in the preliminary statement of the official record of the 1957 resurvey.

Dependent Resurvey of a Portion of the East Boundary,
T. 24 S., R. 7 W., Willamette Meridian, Oregon.

(Restoring the 1853 survey by Henry S. Gile, and correcting the 1957 dependent resurvey by Eggen)

Beginning at the cor. of secs. 1, 6, 7, and 12, on the E. bdy. of the Tp., monumented with an iron post, 2 ins. diam., firmly set, in a mound of stone, 4 ft. base, protruding 18 ins. above the ground, with brass cap marked and witnessed as described in the official record.

N. 2° 08' E., bet. secs. 1 and 6, marking and blazing the true line.

Descend 3 ft. over N. slope.

- 0.28 Gully, drains S. 80° E.; asc. 90 ft. over S. slope.
- 2.19 Spur, slopes SE.; asc. 342 ft. along E. slope.
- 28.66 Creek, 7 lks. wide, course S. 10° E.; asc. 313 ft. over SW. slope, changing to S. slope.
- 39.66 Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 6, at proportionate distance; there is no remaining evidence of the original corner.

From this point, the $\frac{1}{4}$ sec. cor. of secs. 1 and 6, erroneously reestablished by Eggen, in 1957, bears South, 0.14 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, and at the corner point

Reset the iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked

T 24 S
R 7 W R 6 W
S 1 } S 6
1957