

T. 23 S., R. 6 W.

CHAINS

The following record represents a correction of the dependent resurvey of a portion of the south and west boundaries and subdivisional lines of township 23 south, range 6 west, Willamette Meridian, Oregon, as executed by Orville N. Eggen, in 1957, under Group No. 244.

T. 23 S., R. 6 W., was resurveyed by Otis O. Gould, Joseph S. Gawron, and Orville N. Eggen in the period from 1943 to 1957. The notes were approved and the plat accepted August 24, 1960. In February, 1964, it was reported that two original corners had been recovered on the west boundary of the township and had not been used by Eggen during his resurvey. An investigation disclosed original evidence of the corner of sections 25, 30, 31, and 36, and of the $\frac{1}{4}$ section corner of sections 25 and 30, both on the west boundary of the township. The recovery of these two corners affects the control used by Eggen for the proportionate restoration of lost corners along the south and west boundaries and the subdivisional lines of the township.

The method of procedure of this correction of resurvey is as described in the preliminary statement of the official record of the 1957 resurvey.

Dependent Resurvey of a Portion of the South Boundary,
T. 23 S., R. 6 W., Willamette Meridian, Oregon.

(Restoring the 1853 survey by Robert Elder and Henry Gile, and correcting the 1957 dependent resurvey by Eggen)

Beginning at the cor. of secs. 5, 6, 31, and 32, on the S. bdy. of the Tp., monumented with an iron post, 2 ins. diam., firmly set, in a mound of stone, 3 ft. base, protruding 6 ins. above the ground, with brass cap marked and witnessed as described in the official record.

S. $88^{\circ} 49'$ W., bet. secs. 6 and 31, marking and blazing the true line.

Descend 88 ft. over NW. slope.

4.61 Creek, 2 lks. wide, course N. 65° E.; asc. 788 ft. over NE. slope.

25.05 Ridge, bears N. 50° W. and S. 50° E.; desc. 292 ft. over SW. slope.

38.75 Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 31, at proportionate distance; there is no remaining evidence of the original corner.

From this point the $\frac{1}{4}$ sec. cor. of secs. 6 and 31, erroneously reestablished by Eggen, in 1957, bears South, 0.14 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, destroy the marks on the NW. bearing tree, and at the corner point

Reset the iron post, 36 ins. long, 2 ins. diam., 32 ins. in the ground, with brass cap marked