

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, South Boundary, T. 23 S., R. 6 W.

CHAINS

T 23 S R 6 W
 $\frac{1}{4}$ S 31
 $\frac{1}{4}$ S 6
 T 24 S
 1957

from which a new bearing tree

A fir, 20 ins. diam., bears N. 30° E., 29 lks. dist., mkd. $\frac{1}{4}$ S31 BT.

and a bearing tree marked by Eggen, in 1957

A fir, 15 ins. diam., bears S. 27° W., 25 lks. dist., with a healed blaze.

Descend 217 ft. along S. slope.

50.66 Spur, slopes SW.; desc. 91 ft. over W. slope.

61.55 Creek, 8 lks. wide, course S. 25° E.; asc. 532 ft. over E. slope, changing to NE. slope.

77.50 Point for the cor. of Tps. 23 and 24 S., Rs. 6 and 7 W., at proportionate distance; there is no remaining evidence of the original corner.

From this point, the cor. of Tps. 23 and 24 S., Rs. 6 and 7 W., erroneously reestablished by Eggen, in 1957, bears South, 0.275 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, destroy the marks on the NE. and SE. bearing trees, and at the corner point

Reset the iron post, 36 ins. long, 2 ins. diam., 20 ins. in the ground, with brass cap marked

T 23 S
 R 7 W | R 6 W
 S 36 | S 31
 S 1 | S 6
 R 7 W | R 6 W
 T 24 S
 1957

*See field notes
 for description
 of this corner
 8/2/57*

from which new bearing trees

A fir, 8 ins. diam., bears N. 63° E., 111 lks. dist., mkd. T23S R6W S31 BT.

A cedar, 15 ins. diam., bears S. 85° E., 163 lks. dist., mkd. T24S R6W S6 BT.

and bearing trees marked by Eggen, in 1957

A fir, 13 ins. diam., bears S. 73° W., 151 lks. dist., with a healed blaze.

A fir, 22 ins. diam., bears N. 74½° W., 177 lks. dist., with a healed blaze.

From this point the cor. of secs. 1, 6, 7, and 12, on the E. bdy. of T. 24 S., R. 7 W., bears S. 2° 08' W., 79.32 chs. dist., described in the field notes of the correction of the dependent resurvey of a portion of the E. bdy. of T. 24 S., R. 7 W.

From this same point the cor. of secs. 35 and 36, only,