

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, West Boundary, T. 23 S., R. 6 W.

CHAINS

- 44.95 Leave logged area, edge bears E. and W.; road, unimproved, 15 lks. wide, bears E. and W.
- 48.10 Bed of dry creek, 3 lks. wide, drains S. 70° W.; asc. 10 ft. over SW. slope.
- 53.63 Spur, slopes NW.; desc. 133 ft. over NW. slope.
- 59.25 Spur, slopes W.; desc. 387 ft. over N. slope, changing to NW. slope.
- 69.25 Creek, 5 lks. wide, course NE.; asc. 12 ft. over SE. slope.
- 71.38 Spur, slopes E.; desc. 77 ft. over NE. slope.
- 74.24 Creek, 5 lks. wide, course N. 15° W.; asc. 20 ft. over SW. slope.

79.27 The cor. of secs. 25, 30, 31, and 36, determined at record bearing and distance from the original bearing trees:

A down fir, 26 ins. diam., bears N. 80° E., 35 lks. dist., with fragmentary scribe marks visible on opened blaze.

A down and decayed cedar, 20 ins. diam., bears S. 58° E., 70 lks. dist., with no marks remaining.

The stump hole of a fir, bears S. 62° W., 29 lks. dist.

A down cedar, 32 ins. diam., bears N. 21° W., 62 lks. dist., with a healed blaze.

From this point, the cor. of secs. 25, 30, 31, and 36, erroneously reestablished by Eggen, in 1957, bears S. 29° W., 0.63 chs. dist., set, marked, and witnessed as described in the official record. I remove the iron post, destroy the marks on the bearing trees, and at the original corner point

Reset the iron post, 36 ins. long, 2 ins. diam., 24 ins. in the ground, to bedrock, with brass cap marked

T 23 S	
R 7 W	R 6 W
S 25	S 30
S 36	S 31
1957	

from which new bearing trees

A fir, 14 ins. diam., bears N. 73½° E., 78 lks. dist., mkd. T23S R6W S30 BT.

A fir, 7 ins. diam., bears S. 33½° E., 44 lks. dist., mkd. T23S R6W S31 BT.

A cedar, 14 ins. diam., bears S. 37° W., 85 lks. dist., mkd. T23S R7W S36 BT.

A cedar, 23 ins. diam., bears N. 12° W., 17 lks. dist., mkd. T23S R7W S25 BT.