

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS

from which bearing trees marked by Eggen, in 1957

A fir, 15 ins. diam., bears N. 71° E., 36 lks. dist., with a healed blaze.

A fir, 25 ins. diam., bears N. 76° W., 52 lks. dist., with a healed blaze.

Descend 400 ft. over NW. slope.

48.25 Bear Creek, 10 lks. wide, course SE.; asc. 599 ft. over SW. slope.

49.30 Graded road, 30 lks. wide, bears SE. and NW.

53.93 Road, unimproved, 15 lks. wide, bears SE. and NW.

80.16 Point for the cor. of secs. 29, 30, 31, and 32, at proportionate distance; there is no remaining evidence of the original corner.

From this point, the cor. of secs. 29, 30, 31, and 32, erroneously reestablished by Eggen, in 1957, bears West 0.15 chs. dist., set, and marked as described in the official record. I remove the iron post, and at the above corner point

Reset the iron post, 28 ins. long, 2½ ins. diam., 27 ins. in the ground, with brass cap marked

T 23 S R 6 W			
S 30	S 29		
S 31	S 32		
1957			

from which new bearing trees

A fir, 10 ins. diam., bears S. 19° E., 220 lks. dist., mkd. T23S R6W S32 BT.

A fir, 9 ins. diam., bears N. 13° W., 103 lks. dist., mkd. T23S R6W S30 BT.

and the remaining bearing tree marked by Eggen, in 1957

A fir, 13 ins. diam., bears N. 60½° E., 102 lks. dist., with a healed blaze.

The SE., SW., and NW. 1957 bearing trees have been destroyed. There is no suitable tree available within limits in the SW. quadrant.

Land, mountainous.

Soil, sandy loam, rock outcroppings.

Timber, fir, hemlock, and cedar; undergrowth, vine maple, poison oak, and salal.

From the cor. of secs. 28, 29, 32, and 33, monumented with an iron post, 2 ins. diam., firmly set, in a mound of stone, 3 ft. base, protruding 10 ins. above the ground, with brass cap marked and witnessed as described in the official record.

S. 88° 57' W., bet. secs. 29 and 32.

Descend 108 ft. over NW. slope.