

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 7 W.

CHAINS 34.30	Creek, 1 lk. wide, course N. 55° W.; asc. 60 ft. over S. W. slope.
40.58	Point for the $\frac{1}{4}$ sec. cor. of secs. 22 and 23, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 22 S R 7 W S 22 S 23 1965 </div> from which A fir, 23 ins. diam., bears N. 65 $\frac{1}{2}$ ° E., 14 $\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S23 BT. A cedar, 18 ins. diam., bears N. 76 $\frac{1}{2}$ ° W., 32 $\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S22 BT. Ascend 110 ft. over broken S.W. slope.
41.50	Leave logged area; enter heavy timber and dense undergrowth, edge bears generally E. and W.
54.50	Spur, slopes N. 60° W.; desc. 205 ft. over N. slope.
60.15	Ravine, drains N. 50° W.; asc. 10 ft. over S.W. slope.
60.87	Point for the N 1/16 sec. cor. of secs. 22 and 23. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> N 1/16 S 22 S 23 1965 </div> from which A hemlock, 14 ins. diam., bears S. 73° E., 36 lks. dist., mkd. N 1/16 S23 BT. A cedar, 19 ins. diam., bears S. 61° W., 62 lks. dist., mkd. N 1/16 S22 BT. Ascend 15 ft. over S.W. slope.
65.50	Top of ascent, slopes W.; desc. 70 ft. over N.W. slope.
68.75	Leave timber; enter pasture land, edge bears E. and W.
73.10	Gravelled road, 20 lks. wide, bears N.E. and S. W.
73.70	Bottom of descent, slopes W.; asc. 40 ft. over S. slope.
81.16	Point for the cor. of secs. 14, 15, 22, and 23, at proportionate distance; there is no remaining evidence of the original corner. The line bet. secs. 15 and 22 was completed by Byars in 1871. Byars made no mention of the original $\frac{1}{4}$ sec. cor. and witness point of secs. 15 and 22 established by Gordon and Gardner, in 1855, and established his own $\frac{1}{4}$ sec. cor. for secs. 15 and 22. There is no remaining evidence of the Byars $\frac{1}{4}$ sec. cor., but the original $\frac{1}{4}$ sec. cor. and witness point have been recovered and remonumented by the Douglas County Surveyor. The position of this sec. cor. is based on the original cor. of secs. 15, 16, 21, and 22, as control to the west and Byar's returns of the line