

14536 County Surveyor's Record, Douglas County, Oregon

T. 31 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

The following record represents a correction of the dependent resurvey of the line between sections 15 and 16, township 31 south, range 8 west, Willamette Meridian, Oregon, as executed by C. Albert White, Harold D. Corbin, and Donald R. Beck in 1961-64, under Group No. 446.

A portion of the subdivisional lines, T. 31 S., R. 8 W., was resurveyed by C. Albert White, Harold D. Corbin, and Donald R. Beck in 1961-64. The notes were approved and plat accepted August 18, 1964. In January 1970, it was reported that the original $\frac{1}{4}$ section corner of sections 15 and 16 had been recovered, and that the $\frac{1}{4}$ section corner reestablished by proportionate distance during the resurvey was erroneously positioned. An investigation disclosed evidence of the original corner, the recovery of which affects the bearing and distance of the line between sections 15 and 16.

The method of procedure of this correction of resurvey is as described in the preliminary statement of the official record of the 1961-64 resurvey.

Dependent Resurvey of the line between
Sections 15 and 16, T. 31 S., R. 8 W.,
Willamette Meridian, Oregon

(Restoring the 1883 survey by William H. Byars, and
correcting the 1961-64 resurvey by C. Albert White,
Harold D. Corbin, and Donald R. Beck)

Beginning at the cor. of secs. 15, 16, 21, and 22, monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap marked and witnessed as described in the official record of the 1961-64 dependent resurvey.

N. $1^{\circ} 18'$ W., bet. secs. 15 and 16, marking and blazing the true line.

Descend 5 ft. over NW. slope, through medium timber and moderate undergrowth.

0.50 Creek, 1 lk. wide, course NE.; desc. 135 ft. over NE. slope.

7.00 Creek, 4 lks. wide, course S. 35° E.; asc. 750 ft. over SW. slope, changing to S. slope.

25.30 Ridge, bears S. 60° E. and N. 60° W.; desc. 290 ft. over NE. slope.

41.25 The $\frac{1}{4}$ sec. cor. of secs. 15 and 16, determined at record bearing and distance from the original bearing trees:

A fir snag, 33 ins. diam., bears N. 44° E., 44 lks. dist., with fragmentary scribe marks visible on badly weathered bark blaze.

A fir, 35 ins. diam., bears N. 80° W., 25 lks. dist., with scribe marks $\frac{1}{4}$ S BT visible on bark blaze.

From this point the $\frac{1}{4}$ sec. cor. of secs. 15 and 16, erroneously reestablished by White, Corbin, and Beck, in 1961-64, bears S. $21^{\circ} 54'$ E., 1.11 chs. dist., set marked and witnessed as described in the official record.