

15804

## T. 29 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

The following record represents a correction of the dependent resurvey of a portion of the boundaries of Donation Land Claim No. 40, subdivisional lines, and subdivisional lines of section 9, township 29 south, range 7 west, Willamette Meridian, Oregon, as executed by Hans W. Thielsen, in 1955, under Group Number 316.

A portion of the subdivisional lines of the township was surveyed by Nathaniel Ford, in 1855.

The south boundary of Donation Land Claim No. 40 was resurveyed, and section 9 was resurveyed and subdivided by Hans W. Thielsen, in 1955. The notes were approved and the plat accepted August 21, 1956. Subsequent to the 1955 resurvey, the positions of the SE. and SW. corners of Donation Land Claim No. 40 were protested. An investigation in May of 1971 disclosed the original SE. and SW. claim corners could be identified by original or acceptable collateral evidence.

The directions of the lines were determined by the solar transit method, and by deflection angles turned from azimuths obtained by direct solar observations.

All other preliminary data of the correction of resurvey is as described in the preliminary statement of the official record of the 1955 resurvey.

Dependent Resurvey of a Portion of the Subdivisional Lines  
T. 29 S., R. 7 W., Willamette Meridian, Oregon

(Restoring the survey by Nathaniel Ford,  
Deputy Surveyor, in 1854,  
and correcting the 1955 resurvey by Hans W. Thielsen,  
Cadastral Surveyor)

Beginning at the  $\frac{1}{2}$  sec. cor. of secs. 8 and 9, monument-  
ed with an iron post, 1 in. diam., firmly set, protrud-  
ing 6 ins. above ground, with brass cap mkd.

*Fd. OK 2-23  
BY BENTZ M116-49*

$\frac{1}{2}$   
S 8 | S 9  
1955

from which the remains of the bearing trees mkd. by  
Frank Cain, Deputy County Surveyor, in 1913

A root hole, bears S.  $65\frac{1}{2}^{\circ}$  E., 95 lks. dist., with  
a down and decayed fir alongside, 36 ins. diam.,  
no marks visible.

A root hole, bears S.  $40^{\circ}$  W., 10 lks. dist., with  
a down fir alongside, 30 ins. diam., no marks  
visible.

and bearing trees mkd. by the County Surveyor, in 1954

A fir, 11 ins. diam., bears N.  $87^{\circ}$  E., 47 lks.  
dist., with healed blaze.

A fir, 9 ins. diam., bears S.  $77^{\circ}$  W., 46 lks.  
dist., with healed blaze. (Record, S.  $80^{\circ}$  W.,  
20 lks.)

and the remains of bearing trees mkd. by Thielsen, in  
1955

A root hole, bears S.  $42\frac{1}{2}^{\circ}$  E., 50 lks. dist.