

County Surveyor's Record, Douglas County, Oregon

16750

Remonumentation of Certain Original Corner Points,
T. 20 S., R 8 W., Willamette Meridian, Oregon

CHAINS

from which bearing trees marked in 1954

A cedar, 43 ins. diam., bears S. 73° E.,
38 lks. dist., with fragmentary scribe
marks visible on partially healed blaze.

A cedar, 38 ins. diam., bears N. 38 1/2° W.,
104 lks. dist., no marks remaining on
burned blaze. Rescribed 1/4 S18 BT on
new blaze.

At the corner point

Reset the iron post, 26 ins. in the ground.

Set a 5 ft. steel fence post alongside the
iron post.

(Rehabilitating corners reestablished by
Thomas A. Tillman, Joseph S. Gawron, Hans W. Thielsen,
and Raymond M. Bicknell, in 1954)

The cor. of secs. 7, 8, 17, and 18, monumented with an
iron post, 2 ins. diam., firmly set, projecting 10 ins.
above ground, with brass cap mkd.

$$\begin{array}{r} \text{T 20 S R 8 W} \\ \text{S 7 | S 8} \\ \hline \text{S 18 | S 17} \\ \text{1954} \end{array}$$

from which the remains of the bearing trees marked in
1954

A root hole, bears N. 14 1/2° E., 85 lks. dist.,
with a down cedar alongside, 18 ins. diam.,
with healed blaze.

A sawed fir stump, 42 ins. diam., bears
S. 4° E., 50 lks. dist., with healed blaze.

A sawed fir stump, 44 ins. diam., bears
S. 88° W., 76 lks. dist., no marks remaining
on burned blaze. (Record, 84 lks.) Rescribed
T20S R8W S18 BT on new blaze.

A root hole, bears N. 13 1/4° W., 56 lks. dist.,
with a down maple alongside 22 ins. diam.,
with scribe marks T20S R8W S7 BT visible
on open blaze.

and a new bearing tree

A sawed cedar stump, 28 ins. diam., bears
N. 43° W., 73 1/2 lks. dist., mkd. T20S R8W
S7 BT.

Set a 5 ft. steel fence post alongside the
iron post.

The 1/4 sec. cor. of secs. 8 and 17, monumented with an
iron post, 1 in. diam., firmly set, projecting 8 ins.
above ground, with brass cap mkd.

$$\begin{array}{r} \text{1/4 } \frac{\text{S 8}}{\text{S 17}} \\ \text{1954} \end{array}$$