

County Surveyor's Record, Douglas County, Oregon

T. 30 S., R. 9 W., Willamette Meridian, Oregon

17276

CHAINS

sections 4 and 5 lies on a divide, causing the drainage on both sides to drain away from the line.

There were no mineral deposits noted along the lines of the resurvey.

A considerable number of readings throughout the area gives a value of 19° E. for the mean magnetic declination, with a range of up to $15'$ due to local attraction.