

County Surveyor's Record, Douglas County, Oregon

17906

T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

The following field notes are those of the corrective dependent resurvey of a portion of the subdivisional lines, dependent resurvey of a portion of the west boundary and subdivisional lines, and the subdivision of sections 6 and 28, Township 22 South, Range 9 West, Willamette Meridian, Oregon.

The history of surveys pertaining to this resurvey is as follows:

A portion of the subdivisional lines was surveyed by William H. Byars, U.S. Deputy Surveyor, in 1874, 1877, and 1878.

A portion of the west boundary was surveyed by Aurelius Todd, U.S. Deputy Surveyor, in 1894.

A portion of the subdivisional lines was surveyed by Alonzo Gesner and E. O. Worrick, U.S. Deputy Surveyors, in 1894. A portion of the subdivisional lines was surveyed by Alonzo Gesner and E. O. Worrick, U.S. Deputy Surveyors, in 1894.

A portion of the subdivisional lines and the Donation Land Claims were dependently resurveyed by George S. Pershin, U.S. Deputy Surveyor, in 1896.

A portion of the south boundary of Township 21 South, Range 10 West, and a portion of the north boundary of section 6, Township 22 South Range 9 W., were dependently resurveyed by Fred Mensch, Charles M. Collier, Fred W. Rudolf, Elmer P. Strickler, and Gerald A. Sorrels, U.S. Transmitters, in 1919.

A portion of the subdivisional lines was dependently resurveyed by James E. Jelley, Cadastral Surveyor, in 1970.

A portion of the west boundary, Township 22 South, Range 10 West, a portion of the south boundary, Townships 21 South, Ranges 9 and 10 West, and a portion of the subdivisional lines were dependently resurveyed by Harvey E. Wofford, Wayne L. Rogers, and Owen C. Chatters, II, Cadastral Surveyors, in 1973-79. The survey was accepted February 25, 1980. Subsequently original evidence was recovered at the $\frac{1}{4}$ section corner of section 6 only, on the east boundary of the section, the closing corner of sections 5 and 8, the corner of sections 22, 23, 26, and 27, and the $\frac{1}{4}$ section corner of sections 21 and 22, all of which were erroneously reestablished by proportional measurement during the 1973-79 resurvey. The recovery of the corners affected the bearing and distance of the lines corrected in this survey.

The resurvey was executed in accordance with the specifications as set forth in the Manual of Surveying Instructions, 1973, the Special Instructions dated October 28, 1982, supplemental Special Instructions dated February 28, 1983, Second Supplemental Special Instructions dated April 26, 1983, Third Supplemental Special Instructions dated August 3, 1983, under Group No. 1125, Oregon, Special Instructions dated August 7, 1984, and Supplemental Special Instructions dated September 13, 1984, under Group No. 1226, Oregon.

The directions of the lines refer to the true meridian as determined by deflection angles from azimuths obtained by direct solar observations.