

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 30,
18163T. 30 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
51.35	Three-wire power transmission line, bears N. 10° W. and S. 10° E.
51.65	Spur, slopes N. 5° W.; desc. over broken NW. slope, also dirt road, 15 lks. wide, bears N. 5° W. and S. 5° E.
59.92	Point for the center W 1/16 sec. cor. of sec. 30. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd. <div style="text-align: center; margin: 10px 0;"> $C \frac{W \ 1/16}{S \ 30} C$ <p style="margin: 0;">1985</p> </div> from which A fir, 14 ins. diam., bears S. 10½° W., 32½ lks. dist., mkd. CW 1/16 S30 BT. A cedar, 9 ins. diam., bears N. 14 ¾° W., 28 lks. dist., mkd. CW 1/16 S30 BT. Deposit white "DEEP-1" magnetic marker at base of stainless steel post. Descend over broken NW. slope.
68.60	Creek, 3 lks. wide, course N. 5° W.; asc. over NE. slope.
78.925	The ¼ sec. cor. of sec. 30 only, on the W. bdy. of the Tp.
4.30	From the center E 1/16 sec. cor. of sec. 30. N. 0° 06' E., on the N. and S. center line of the NE¼ of sec. 30. Descend over NE. slope, through heavy timber and dense undergrowth.
17.55	Packard Creek, 4 lks. wide, course N. 60° W.; asc. over broken SW. slope.
23.95	Spur, slopes N. 55° W.; desc. over NW. slope.
39.65	Ravine, drains W.; asc. over broken SW. slope.
40.53	Spur, slopes N. 80° W.; desc. over NW. slope.
20.17	The E 1/16 sec. cor. of secs. 19 and 30. From the E 1/16 sec. cor. of secs. 30 and 31. N. 0° 03' E., on the N. and S. center line of the SE¼ of sec. 30. Ascend over broken SW slope, through heavy timber and dense undergrowth.
20.17	Point for the SE 1/16 sec. cor. of sec. 30, at intersection with the E. and W. center line of the SE¼. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.