

County Surveyor's Record, Douglas County, Oregon

18348

Corrective Dependent Resurvey of a Portion of
the Subdivisional Lines, T. 30 S., R. 5 W.,
Willamette Meridian, Oregon

CHAINS

COUNTY SURVEYORS OFFICE

T 30 S
S 10
S 15
R 5 W
1963

from which the remains of an original bearing tree

A root hole, bears N. 45° W., 16 lks. dist.

and remains of bearing trees mkd. by John H. Markham, Registered Engineer No. 2880, in 1958

A madrone, 36 ins. diam., bears N. 28° E., 51½ lks. dist., with scribe marks ¼ S10 BT visible on partially healed double blaze.

A root crown, size indeterminate, bears N. 59° E., 47 lks. dist., no marks visible.

and the remains of a bearing tree mkd. by Roseberry and Jelley

A root hole, bears S. 70 ¾° E., 29½ lks. dist., with down fir stump alongside, 48 ins. diam., with healed blaze.

and a new bearing tree

A fir, 9 ins. diam., bears S. 47° E., 64 lks. dist., mkd. 1/4 S15 BT.

N. 89° 11' W., bet. secs. 10 and 15, marking and blazing the true line.

Ascend over broken NE. slope, changing to SE. slope, through heavy timber and dense undergrowth.

10.20 Gravelled road, 25 lks. wide, bears N. 70° W. and S. 65° E.

11.55 Spur, slopes S. 65° E.; desc. over SW. slope.

19.725 Point for the W 1/16 sec. cor. of secs. 10 and 15.

From this point, the W 1/16 sec. cor. of secs. 10 and 15, erroneously established by Roseberry and Jelley, in 1967-69, bears S. 80° 59' W., 0.172 chs. dist., monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post, destroy the marks on the bearing trees and at the true corner point

Reset the iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap

S 10
W 1/16 S 15
1986

from which

A fir, 49 ins. diam., bears S. 14° E., 29 lks. dist., mkd. W 1/16 S15 BT.

A fir, 31 ins. diam., bears N. 8° W., 25 lks. dist., mkd. W 1/16 S10 BT.

Descend over SW. slope.