

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of the Line
Between Sections 4 and 9,
T. 28 S., R. 8 W., Willamette Meridian, Oregon

18401

CHAINS	
	<p>S. 89° 55' W., bet. secs. 4 and 9.</p> <p>Descend over NW. slope, through dense timber and undergrowth.</p>
1.25	<p>Ravine, drains N. 15° W.; asc. over NE. slope.</p>
4.55	<p>Spur, slopes N. 30° W.; desc. over broken NW. changing to SW. slope.</p>
20.855	<p>The E 1/16 sec. cor. of secs. 4 and 9, established and recorded by Richard J. Hintz, Registered Land Surveyor, No.497, in 1986, and accepted as the corner, monumented with an aluminum rod, 3/4 in. diam., firmly set, projecting 4 ins. above ground, with an aluminum cap mkd. IP TIMBERLANDS OPERATIONS CO. RLS 497 E 1/16 S4 S9 1986, from which bearings trees mkd. by Hintz:</p> <p style="margin-left: 40px;">A fir, 20 ins. diam., bears N. 72° E., 4 lks. dist., with scribe marks E 1/16 S4 BT visible on partially healed blaze.</p> <p style="margin-left: 40px;">A fir, 9 ins. diam., bears S. 67° E., 27 lks. dist., with scribe marks E 1/16 S9 BT visible on partially healed blaze.</p> <hr style="width: 20%; margin: 20px auto;"/> <p>S. 89° 55' W., beginning new measurement.</p> <p>Continue descent of broken SW. slope.</p>
20.855	<p>Point for the 1/4 sec. cor. of secs. 4 and 9, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>From this point, the 1/4 sec. cor. of secs. 4 and 9, erroneously reestablished by Jelley in 1975, bears S. 89° 34' W., 0.67 chs. dist., monumented with an iron post, 2 1/2 ins. diam., set, marked, and witnessed as described in the official record. Remove the iron post, destroy the marks on the bearing trees, and at the true corner point</p> <p>Reset the iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> $\frac{1}{4} \frac{S 4}{S 9}$ <p>T 28 S R 8 W 1975 1987</p> </div> <p>from which</p> <p style="margin-left: 40px;">A fir, 17 ins. diam., bears S. 17 1/4° W., 43 lks. dist., mkd. 1/4 S9 BT.</p> <p style="margin-left: 40px;">A fir, 11 ins. diam., bears N. 60 1/2° W., 24 lks. dist., mkd. X BT.</p> <p>From this same point, a local corner established by Marvin Ramsey, Registered Land Surveyor, No. 404, in 1962, bears N. 1° 44' W., 0.20 chs. dist., monumented with an iron pipe, 1 1/2 ins. diam., firmly set, projecting 6 ins. above ground, from which bearings trees mkd. by Ramsey:</p> <p style="margin-left: 40px;">A fir, 21 ins. diam., bears N. 57° E., 8 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A fir, 13 ins. diam., bears S. 53° W., 9 lks. dist., with healed blaze.</p> <p>Descend over SW. slope.</p>