

County Surveyor's Record, Douglas County, Oregon

18519 Subdivision of Section 19,
T. 29 S., R.7 W., Willamette Meridian, Oregon

CHAINS	
9.545	<p>From the center W-SE 1/64 sec. cor. of sec. 19.</p> <p>N. 1° 50' 30" E., on the N. and S. center line of the NW¼ of the SE¼ of sec. 19.</p> <p>Ascend over broken SW. slope, through heavy timber and moderate undergrowth.</p> <p>Point for the NW-SE 1/64 sec. cor. of sec. 19, at calculated position.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">NW SE 1/64 S 19 1988</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears N. 37° E., 52 lks. dist., mkd. NW SE 1/64 S19 BT.</p> <p style="padding-left: 40px;">A fir, 9 ins. diam., bears N. 54° W., 25½ lks. dist., mkd. X BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p>
9.930	<p>From the center N-SE 1/64 sec. cor. of sec. 19.</p> <p>N. 80° 31' 00" W., on the E. and W. center line of the NW¼ of the SE¼ of sec. 19.</p> <p>Ascend over broken SE. slope, through heavy timber and moderate undergrowth.</p> <p>The NW-SE 1/64 sec. cor. of sec. 19.</p>
9.525	<p>From the W 1/16 sec. cor. of secs. 19 and 30.</p> <p>N. 1° 12' 30" E., on the N. and S. center line of the SW¼ of sec. 19.</p> <p>Ascend over broken SE. slope, through heavy timber and moderate undergrowth.</p> <p>Point for the center S-SW 1/64 sec. cor. of sec. 19.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">CS SW 1/164 S 19 1988</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 18 ins. diam., bears S. 11° E., 32½ lks. dist., mkd. CS SW 1/64 S19 BT.</p> <p style="padding-left: 40px;">A cedar, 10 ins. diam., bears N. 1° W., 35½ lks. dist., mkd. CS SW 1/64 S19 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p>