

# County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of a Portion of the East Boundary,  
T. 19 S., R. 10 W., Willamette Meridian, Oregon

18755

## CHAINS

N. 29° 21' W., 0.437 chs. dist., monumented with an iron post, 2½ ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd. as described in the official record. Amended the marks on the brass cap to read AM 1989 1958 and reset the monument flush with the ground surface.

N. 0° 44' 30" E., beginning new measurement.

Descend NE. slope, through logged area, posting true line.

5.00 Spur, slopes N. 20° E.; desc. N. slope.

7.50 Dry creek bed, 2 lks. wide, course N. 40° E.; asc. SE. slope.

9.715 Point for the ¼ sec. cor. of sec. 7 only, T. 19 S., R. 9 W.

From this point, the ¼ sec. cor. of sec. 7 only, T. 19 S., R. 9 W., erroneously established by Tillman, Holm, and Brooks in 1957-58, bears N. 29° 23' E., 1.029 chs. dist., monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above ground, mkd. and witnessed as described in the official record, except the NE. bearing tree is a fir, bears N. 66½° E., 68 lks. dist., (record, hemlock, N. 48½° E., 147 lks.), and found no evidence of the SE. bearing tree. Remove the iron post and at the true corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd:

T19S	
R10W	R9W
¼	
S 7	
1989	

*FD OK  
D. Baker  
M124-45  
3/97*

from which

A stainless steel post, 28 ins. long, 2½ ins. diam., set 28 ins. in the ground, for a reference monument, bears N. 29° 23' E., 102.9 lks. dist., with brass cap mkd. RM ¼ S7 67.9 FT TO COR 1989 and an arrow pointing to the corner.

and a bearing tree mkd. by Tillman, Holm and Brooks

A fir, 34 ins. diam., bears N.44° E., 163 lks. dist., with healed blaze.

and a bearing tree mkd. by Daniel W. Baker, Registered Land Surveyor No. 1978, in 1988, and recorded in Douglas County Survey Map 107-1.

A hemlock, 25 ins. diam., bears S.68° E., 75 lks. dist., with scribe marks ¼ S7 BT visible on partially healed blaze.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

From this same point, a point established as the ¼ sec. cor. of sec. 7 only, T. 19 S., R. 9 W., by Daniel W. Baker, Registered Land Surveyor No. 1978, in 1988, and recorded in Douglas County Survey Map 107-1, bears S. 87° 44' W., 0.177 chs. dist., monumented with an aluminum post, 2½ ins. diam., firmly set, projecting 6 ins. above ground, with aluminum cap mkd. T19S R9W R10W ¼ S7 S1978 1988. This point was established using improper control and is not utilized in this survey.

Ascend SE. slope, through logged area.

13.00 Spur, slopes S. 80° E.; desc. broken NE. slope.

27.70 Spur, slopes S. 40° E.; desc. NE slope, through timber.