

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

FIELD NOTES
OF THE
REHABILITATION OF THE 1/4 SECTION CORNER,
OF SECTIONS 29 AND 30,
TOWNSHIP 28 SOUTH, RANGE 3 WEST,
OF THE WILLAMETTE MERIDIAN,
IN THE STATE OF OREGON.

EXECUTED BY

Timothy J. Moore, Cadastral Surveyor

Under Special Instructions dated July 13, 1979, approved July 17, 1979,
and Supplemental Special Instructions
dated May 20, 1985, approved May 24, 1985,
which provided for the rehabilitation included under Group No. 1000,
and assignment instructions dated May 11, 2000.

Commenced May 11, 2000

Completed May 11, 2000

T. 28 S., R. 3 W., Willamette Meridian, Oregon

FEET

The following field notes describe the rehabilitation of the 1/4 section corner of section 29 and 30, township 28 south, range 3 west, Willamette Meridian, Oregon, as provided for in the Special Instructions dated July 13, 1979, and Supplemental Special Instructions dated May 20, 1985, under Group Number 1000, Oregon. "Rehabilitation of Corner Points, Without Remonumentation, When Suitable Monumentation Exists."

The rehabilitation of the 1/4 section corner of sections 29 and 30, was for administrative purposes of the Bureau of Land Management.

A Detectable Electronically Energized Particles (DEEP-1 TM) was buried as a memorial at the corner monument. The DEEP-1 is composed of strontium encased in a color coded plastic container. The units are one inch in diameter, 2½ inches long, weigh 2½ ounces, and are magnetically detectable to an average depth of 8 feet.

Each new bearing tree has a 2½ inch x 1/4 inch magnetic nail (Mag Nail) driven at the base on the right side-center.

The mean magnetic declination as taken from U.S. Geological Survey Quadrangle map "White Rock, OREG.", provisional edition 1987, is 19° 30' 00" East.

**Rehabilitation of the 1/4 Section Corner of Sections 29 and 30,
T. 28 S., R. 3 W., Willamette Meridian, Oregon**

(Rehabilitating a corner established by William N. Gibb,
U.S. Deputy Surveyor, in 1910)

The 1/4 sec. cor. of secs. 29 and 30, perpetuated by James W. Byron, of the Douglas County Surveyors Office in 1962, from original evidence no longer in existence, recorded in the Douglas County Surveyors Record of Government Corners Renewed, T. 28 S., R. 3 W., corner no. 100, monumented with an iron pipe, 1¼ ins. diam., loosely set, bent over in place with brass cap mkd.

County Surveyors Office

T 28 S

R

3

S 30 S 29 w

¼ 1962

Rehabilitation of the 1/4 Section Corner of Sections 29 and 30,
T. 28 S., R. 3 W., Willamette Meridian, Oregon

FEET	
	from which the remains of a bearing tree mkd. by Byron
	A sawed fir stump, 18 ins. diam., bears N. 19° W., 31.3 ft. dist., with a healed blaze.
	and new bearing trees
	A cedar, 28 ins. diam., bears N. 68½° W., 75.2 ft. dist., mkd. 1/4 S30 BT.
	A fir, 9 ins. diam., bears S. 20¼° E., 120.4 ft. dist., mkd. 1/4 S29 BT,
	Straighten and reset the iron pipe 24 ins. in the ground and deposit a magnet in a white plastic case at the base of the iron pipe.
	Cor. is located 50 ft. W. of a gravel road, 20 ft. wide bears N. 10° E. curving E. and S.
	Note: This area is currently being logged. Logs are decked up around the corner point, so other evidence of accessories may be covered.
	<hr/>