

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

FIELD NOTES  
OF THE  
REHABILITATION OF THE 1/4 SECTION CORNER  
OF SECTIONS 28 AND 29,

**TOWNSHIP 28 SOUTH, RANGE 8 WEST,**  
OF THE WILLAMETTE MERIDIAN,  
IN THE STATE OF OREGON.

**EXECUTED BY**

***A. Bert Skeesick, Cadastral Surveyor***

Under Special Instructions dated July 13, 1979, approved July 17, 1979,  
and Supplemental Special Instructions dated May 20, 1985,  
approved May 24, 1985, which provided for the rehabilitation included  
under Group No. 1000, and assignment instructions dated January 31, 2001.

***Commenced January 31, 2001***

***Completed January 31, 2001***

**T. 28 S., R. 8 W., Willamette Meridian, Oregon**

<p>FEET</p>	<p>The following field notes describe the rehabilitation of the 1/4 section corner of sections 28 and 29, township 28 south, range 8 west, Willamette Meridian, Oregon, as provided for in the Special Instructions dated July 13, 1979, and Supplemental Special Instructions dated May 20, 1985, under Group No. 1000, Oregon, "Rehabilitation of Corner Points, Without Remonumentation, When Suitable Monument Exists."</p> <p>The rehabilitation of the 1/4 section corner of sections 28 and 29 was for administrative purposes of the Bureau of Land Management.</p> <p>The new bearing tree has a 2½ inch x ¼ inch magnetic nail (MAG-NAIL) driven at the base on the right side-center.</p> <p>The mean magnetic declination as taken from U.S. Geological Survey quadrangle map "CAMAS VALLEY, OREG.", Provisional Edition 1990, is 18° East.</p>												
	<p align="center"><b>Rehabilitation of the 1/4 Section Corner of Sections 28 and 29, T. 28 S., R. 8 W., Willamette Meridian, Oregon</b></p> <hr/> <p align="center">(Rehabilitating a corner established by Winfield S. Chapman, U.S. Deputy Surveyor, in 1875 and perpetuated by James E. Jelley in 1975)</p> <hr/> <p>The ¼ sec. cor. of secs. 28 and 29, monumented with an iron post, 1½ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.</p> <div style="text-align: center;"> <table border="0"> <tr> <td>COUNTY</td> <td>SURVEYORS</td> </tr> <tr> <td>T 28 S R 8 W</td> <td></td> </tr> <tr> <td>1/4 S 29</td> <td>  S 28</td> </tr> <tr> <td></td> <td> </td> </tr> <tr> <td></td> <td>1957</td> </tr> <tr> <td></td> <td>OFFICE</td> </tr> </table> </div> <p>from which the remains of a bearing tree mkd. by Frear</p> <p align="center">A decayed fir stump, 26 ins. diam., bears N. 83½° E., 13.2 ft. dist., with a healed blaze.</p> <p>and a bearing tree mkd. by Byron</p> <p align="center">A fir, 24 ins. diam., bears N. 77° W., 45.5 ft. dist., with a healed blaze.</p> <p>and the remains of a bearing tree mkd. by Jelley</p>	COUNTY	SURVEYORS	T 28 S R 8 W		1/4 S 29	S 28				1957		OFFICE
COUNTY	SURVEYORS												
T 28 S R 8 W													
1/4 S 29	S 28												
	1957												
	OFFICE												

Rehabilitation of the 1/4 Section Corner of Sections 28 and 29,  
T. 31 S., R. 6 W., Willamette Meridian, Oregon

FEET	
	<p>A madrone stump, 10 ins. diam., bears N. <math>27\frac{3}{4}^{\circ}</math> E., 23.1 ft. dist.</p> <p>and a new bearing tree</p> <p>A fir, 23 ins. diam., bears S. <math>26^{\circ}</math> W., 17.5 ft. dist., mkd. 1/4 S29 BT.</p> <hr/>