

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

FIELD NOTES  
OF THE  
REHABILITATION OF THE  
STANDARD 1/4 SECTION CORNER OF SECTION 4 ONLY  
ON THE NORTH BOUNDARY OF  
**TOWNSHIP 28 SOUTH, RANGE 8 WEST,**  
OF THE WILLAMETTE MERIDIAN,  
IN THE STATE OF OREGON.

**EXECUTED BY**

***Timothy J. Moore, Cadastral Surveyor***

***Robert H. Browning, Surveying Technician***

Under Special Instructions dated February 22, 2002,  
approved February 22, 2002, which provided for the  
surveys included under Group No. 2000,  
and Assignment Instructions dated October 2, 2007.

***Survey commenced October 2, 2007***

***Survey completed October 3, 2007***

**T. 28 S., R. 8 W., Willamette Meridian, Oregon**

The following field notes describe the rehabilitation of the Standard 1/4 section corner of section 4 only, on the north boundary of Township 28 South, Range 8 West, Willamette Meridian, Oregon, as provided for in the Special Instructions dated February 22, 2002, under Group No. 2000, Oregon, under Assignment Instructions tracked as Group 2000-08-01, dated October 2, 2007.

The rehabilitation of the 1/4 section corner of section 4 only, on the north boundary of the township, was made at the request of the Roseburg District Manager, for the administrative purposes of the Bureau of Land Management.

Each new bearing tree has a 2 1/2 x 1/4 inch magnetic nail (MAG-NAIL) driven at the base on the right side-center.

---

**Rehabilitation of the Standard 1/4 Section Corner of Section 4 only,  
on the North Boundary,  
T. 28 S., R. 8 W., Willamette Meridian, Oregon**

---

(Rehabilitating a corner established by Dennis Hathorn, U.S. Deputy Surveyor, in 1855, and perpetuated by C. Albert White, John M. Jelley, and James E. Jelley, Cadastral Surveyors, in 1961)

The standard 1/4 sec. cor. of sec. 4 only, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 12 ins. above ground, in a collar of stone, 2½ ft. base, 6 ins. high, with brass cap mkd.

—————  
1/4 S 4  
T 28 S R 8 W  
1961

from which the remains of an original bearing tree

A fir snag, 25 ins. diam., bears S. 18° E., 13.2 ft. dist., with scribe marks 1/4 S4 SC BT visible on open blaze. (Record, S. 25° E.)

and the remains of a bearing tree mkd. by Arthur Boyer, Oregon Registered Engineer No. 1581, reported by White, Jelley, and Jelley

A sawed hemlock stump, 10 ins. diam., bears N. 67° W., 13.2 ft. dist., with no scribe marks visible on open blaze.

and the remains of a bearing tree mkd. by White, Jelley, and Jelley

A hemlock snag, 5 ins. diam., bears S. 38° W., 23.1 ft. dist., with a healed blaze.

and new bearing trees

21597

Rehabilitation of the Standard 1/4 Section Corner of Section 4 only,  
on the North Boundary,  
T. 28 S., R. 8 W., Willamette Meridian, Oregon

A fir, 6 ins. diam., bears S.  $81\frac{3}{4}^{\circ}$  W., 16.7 ft. dist., mkd.  
1/4 S4 SC BT.

A hemlock, 18 ins. diam., bears N.  $12\frac{3}{4}^{\circ}$  W., 4.3 ft. dist., mkd.  
1/4 S4 SC BT.

---