

Sup 20 S.R. 12<sup>11</sup>W.

May 26 1973  
J. Cole Surveyor  
Wallace Smiddy Witness  
Mantland Smully  
REN. # 4

1/4 Corner bet. Secs. 8 & 17

I renewed this corner from the original Bearing trees both of which are alive and standing and check closely. I chopped open the fir BT and the scribe marks were plainly visible.

Set a 2" x 60" Iron Pipe for corner

Corner to Secs. 8-9-16-17

I renewed this corner from the original Bearing trees and set a steel buggy axle 1" x 60" from which Orig Cedar BT bearing scribe marks bears S 44° W 20.2 lks

An alder bearing rotted out scar bears S 2° E 20.5 lks

A maple 20" dia showing scars bears N 89° W 13.12 lks

Stump of large fir no marks visible bears N 9° E 4.80 Chains

Corner to 9-10-15-16

Set Iron pipe 2" x 36" from which the original trees bear as follows.

An Alder 24" N 76° E 21 lks

" " 16 S 27 1/2° E 10 "

A Hemlock 8" S 62° W 15 lks

An Alder 15 N 20° W 15 lks

Probably T 20 S.R. 11 W See Page 7  
Vault 1 ENV 35

a.s. 1/35

REN. # 5

REN. # 6