

(Probably never)

1/4 Cor. bet. 4 & 5. No evidence of orig. corner found. Set by prop distants bet. NE & SE Cors. of Section 5 a/o letter of 6/6/39 from Jos A Garong Cad. Engrs. Office.

Set 4" x 4" Yew Post for Corner from which:
36" Fir bears N 45° W 22 ft. Marked 1/4 S. 5. T 25 S. R 3 W. C. S. B. T.
18" Fir " S 26 1/2° E 12 ft. " " S 4. " " " "

Sec. Cor. 4, 5, 8, 9. Located & Renewed from orig. Cedar B.T. (S 10° E. 24 lks) which is now laying on ground & stump is still standing.

Set 4" x 4" Laurel Post for corner, from which:
8" Fir bears N 60° W. 23.5 ft, MKd S 5 T 25 S R 3 W C S B. T.
16" " " N 31° E. 30.0 " on slope, Marked S. 4. R 3 W C. S. B. T.
36" " " N 81° E 79.0 " " " scribe marks by some C.S. still show on blaze (no record of this tree)
24" Fir bears S 39° E (on slope) MKd S 9 T 25 S R 3 W. C. S. B. T.
40" " " South 78 ft (on slope) " S 8 " " " "

and marked low w/c logging operation & Barked Blazed & scribed 1/4 CORNER 8 & 9. Renewed from orig. B.T. N 55° E 21 link which is in good shape, orig scribe marks are on Bark.

Set 4" x 4" Fir Post for corner & Marked New B.T.
14" Maple Bears S 73° W 40.0 ft (on slope) Marked 1/4 S. 8 T 25 S R 3 W C. S. B. T.

Sec. Corner. on N Line of Township for Secs 32 & 33 T 24 S R 3 W. Renewed from Orig B.Ts, A 16" Fir N 75° W 19 lks. & 24" Cedar S 60° E.

Set 4" x 4" Fir Post for corner from which New B.Ts.
40" Cedar bears N 10° E 26.0 ft. Marked 32 & 33 T 24 S R 3 W C. S. B. T.
15" Hemlock " S 58° W 17.0 " " S 5. T 24 S. R 3 W. C S B. T.

Sec Corner 21, 22, 27 & 28. - Renewed from Original B.T. 30" Hemlock N 5° E 39. ft. & 36" Hemlock S 70° E 52 ft. found pile of Rocks at corner.

Set 4" x 4" Fir Post for corner from which New B.Ts 9 ft.
16" Cedar Bears S 40° W 27.0 ft. Marked S 28 T 24 S. R 3 W. C. S. B. T.
6" Yew " West 44.0 " " S 21. T 24 S. R 3 W C S B. T.

A. Boyer D.C.S. Wit. Floyd Norris (Ren # 8) Clint Bamber June 1939

A. Boyer D.C.S. Wit. Ted Shellabarger Rodney Leatherwood June 1939

(Ren. # 5) T 24 S 3

This must be 24 S 15 1/2 W

T. 25 S., R. 3 W.



Wm. E. Richardson
Charley Rice
Jan 1929
F. J. G. [unclear] Co. [unclear]

Section corner to section 25-36 T25S
R3W set corner from fir tree scribe marks
plain for others. #3, rest burned out. This tree
was probably old tree in sec 30. The other trees
were all down but witness of cut marks
on same but no scribe marks, I set
a new wood post for corner and
Marked 10" Fir S 80 W 55 feet
6" " N 15 W 15 1/2 "

Rev. J. J. [unclear] Dep. Co. Engineer
J. A. Irving
J. J. Brown
J. J. [unclear]
T. 25 S.
R. 3 W.
Ren. # 13

T25S R3W.
Sec. Corner $\frac{29}{3} \frac{28}{33}$ Position identified from
original BTs as recorded in office of
Dist. Cadastral Engr. Set 4' x 36" cedar post
for new corner.

Arthur Boyer Dep. Co. Engineer
Jan 25, 1939
Carl Thornton
Tom Leatherwood
T. J. Shellbarger
Wit.
Ren. # 14
Ren. # 15

Sec. Corner $\frac{32}{5} \frac{33}{4}$ T 25 S 26 S R 3 W
Location identified from 4 original BTs as
recorded in Gov't field notes. One BT N W down
and badly rotted. Most of figures scaled off
bark of tree in Sec 4. Blazed and scribed
an 8" Yew N 30° W 28 lks T25S R3W S 32 CS BT
and remarked in bark Original BT in Sec 4.

T25S., R3W
N 1/4 Cor Sec 5 Located Cor from Fir BT. N 28° W 12 links
Set Squared 3" Ced Post 9/4 Scribed new B.T. 30" Fir
S. 2° W. 14.7 ft " 1/4 S 5 T 25 R 3 " CS. B.T "

5/4 Cor Sec 5 Located by running line from SW Cor to
SE Cor Sec 5, Set 3" sq. Yew Post 9/4 Scribed 28" Fir N 85 1/2° E. 23. ft
(Blazed + Scribed on bark) 9/4 30" Fir S 12 1/2° E 38.5 ft
28" Fir Marked " 1/4 S 5 T 25 R 3 " CS BT. 30" Fir " 1/4 S 8 T 25 R 3 " CS BT.