

T 29R6

Mar 13-1923
C.W. Springer, Dep C.S.
H.E. Bergt, Chairman
John Powell

✓ Sec. Cov common to Sec. 546 T 29 R 6 W and 31 R 37
✓ T 28 R 6 W. Two orig BTs standing - one badly
rotted - other two BTs down. Renewed from
the 2 good trees and the stumps of the rotten two.
Drive an iron pipe 1 1/2" x 48" in ground from which
I mkd four new trees as follows - A Fir 8" in dia
bears N 86° 30' W 11.7 ft - A Fir 12" in dia bears S 31° 50' W 37.3 ft
A Fir 10" in dia S 69° 30' E 24 ft - A Fir 6" in dia N 72° E 11.5 ft
An Orig BT. A Fir 24" in dia N 47° E 34.3 ft.

Mar 31-1923
C.W. Springer, Dep C.S.
C. Sherrill
John Powell - Ray Powell
O.W. Parker
J.D. and Edgan Walker

✓ 1/4 Sec. Cov bet. Secs 5 and 6
Replaced corner from original B.T's - one in
bad shape and other one fair. Drove an iron
pipe 1 1/2" x 40" in ground and marked two new
B.T's. - Fir - 12" dia N 59° 40' W 26.6 ft
#36 B. Oak - 10" dia N 24° 00' E 27.3 ft.
Both original B.T's are in evidence at the time.

May 30, 1923
C.W. Springer, Dep. C.S.
J.H. Schubert
W.E. Richards
June 4, 1923
W.F. Riley
#37

S.E. Int. L. Cov W.R. Willis D.L.C 44.
Replaced corner from one original B.T. standing
with scribe marks rotted but still in evidence
and evidence of the other tree at the proper
course and distance - Tree gone tho. Drove
an steel shaft 1 1/2" x 36" in ground and set an
oak stake by it. Marked two new bearing trees
as follows - Oak 10" dia N 86° 00' E 60.4 ft
Ash 8" " S 37° 45' W 15.2 ft.

March 1924
J.W. Rice
M. B. Hawkins
J.W. Rice
#38

✓ 1/4 Corner between Secs. 21-28
I could find no trace of original corner. I renewed
this corner on true sec line one half way between
Sec Corners. Set an iron pipe one in by thirty
six inches 24 inches in the ground from which
Fir N 12° W 118 ft. Laurel 36 in dia S 29 1/2° W 368 ft.

T 29 S R 6 W. Continued on page 193

March 7, 1924

J. Cole C.S.

M B Hawkins of witnesses
Roy Rice

✓ 1/4 Cor bet Secs 20 + 29.

I found a fir stake standing from which a Fir bearing tree corresponding with field notes of Surveyor Fred Munch, Could find no evidence of original trees or rock. Fir tree dead. I marked new trees

Fir 20" N 36° 30' W 48 ft

" 14" S 8° 15' E 48 ft

#39

I set an Iron Pipe 1 1/4" x 40", 30" in ground at corner

✓ 1/4 Corner bet Secs 28 and 29.

I found no evidence of the original corner but placed the corner on the true section line 1/2 way between sec corners. The corner fell in creek on bed rock. I set an iron pipe 1 1/2" x 36" and erected mound of Rock around pipe from which I marked.

Fir 48" dia S 39° 45' W 20 1/2 ft

" 48" " N 63° 00' W 39.7 ft

#40

✓ Cor to Secs 27 - 28 - 33 - 34

Renewed this corner from 20 in Cedar Bearing tree which was standing with scribe marks plainly showing N 40° W 37 lks. Maple down bearing scribe marks S 30° W 13 lks. Maple decayed, no scribe marks showing. bear S 35° E 33 lks, Cedar down N 50° E 13 lks. corner in creek on pile of logs, Marked new trees a Fir 10" dia S 40° W 28 ft.

Cedar 20 in dia N 38° E 49 ft

5 ft x 5 ft x 5 ft
Face of Boulder S 24° E 99 marked S 34° E S 80

Errected mound of rock 20 ft. North of corner

#41

Continued page 193