

29-8

Dec 14/1927

1/4 Section between Sec. 17 and 20

Set Sandstone 3"x10"x16" chiseled 1/4 and X from original B.T. Old blazed badly scared up.

Set new B.Ts. 14" Fir S 85 1/2 E 338 lks scribed 1/4 520 CSBT

14" Fir N 60 E 392 lks " 1/4 517 CSBT

1/4 Section Corner between Secs 20 + 21

#15 Set Ford axle with gear attached for corner from one original B.T. which I remarked in the bark. 30" Fir S 20 E 16 lks.

(New B.T. 28" Fir N 60 W 60 lks. marked 1/4 520 CSBT)

set New B.T. 18" Fir N 13 E 91.0' marked 1/4 521 C.S. B.T. bark blaze

1/4 Section Corner between Secs. 18 and 19.

Set sandstone 10"x10"x20" chiseled X and 1/4

14" underground. Set from original B.T. S 77 E 242 lks. which we chopped into and found scribe marks.

B.T.

New B.Ts. 12" W. oak S 69 2/4 E 201 lks scribed 1/4 519 CSBT

20" " N 40 29 E 311 lks " 1/4 518 CSBT

1/4 Section Corner between Secs 17 & 18

Found 12" ash ~~and~~ in position with proper blaze but signs burned & rotted off. Also old oak which appeared to have formally been the original B.T. found mark 9" long which seemed to be a scribe mark. Oak down + stump burned off. bank wash out where it formally stood.

Bearing and distances checked exactly.

Set sandstone for corner. 6"x8"x20" chiseled 1/4 1/4 X 10" underground.

New B.Ts. 14" Fir S 32 25 E 470 lks scribed 1/4 517 CS BT.

14" Fir N 56 24 W 1022 lks " 1/4 518 CS BT

Witnesses
A. Boyer
W. H. Richter
May 15 1936
C. S. Crear
C. McLann
W. M. Parker

This tree has been cut down & grubbed out