

see the
155 S renewals
in T32-6
Pg 172

32-4

Witnessed by
J. R. Pickett
Frank Jantzen

Reset 1/4 corner bet. Sec's, 20 + 21 T32 S, R4 W, W.M

One hor. wit. tree in evidence.

Set in Green Stone 8"x8"x16" marked with 1/4 S. from which

R. Fir 8" N 59° 30' W, 3.3 ft.

R. " 5" S 89 00' E, 15.4 "

Trees are marked according to law

M. B. Hammond Co. Surv

Feb. 2, 1929
with Stam Ruder
W.C. Richardson
H.L. Oppenheimer

Reset 1/4 Corner bet. Secs 32 + 33 T. 32 S, R. 4 W, W.M,

from old wit. trees. Set stone 14"x10"x8

Remarked old Wit. trees, as follows

Fir 36" N 48° E 25 links; Fir 30" S 82° W 48 links

Marked New Wit tree Fir 40" S 55° W 47 links

July 1910

C.E. Roberts

1/4 Cor. Bet. Secs. 5-6 (F.B. No. 12 Page 67)

Fir 12" S. 14 1/2° E. 71 lks. marked C.S.

" 10" S. 21° W. 74 " " "

July 1910

C.E. Roberts

1/4 Cor. Bet. Secs. 6-7 (F.B. No. 12 Page 66)

Set Yew post 4" square marked 1/4 S, C.S.

Fir 5" S. 26 1/2° W. 14 lks.

Pine 8" N. 48 1/4° W. 74 "

Witnessed by
B. F. Lane
W.C. Richardson
Ted Shellabarger
Dick Dehrig

July 1937

C.E. Roberts

1/4 Cor. Bet. Sec 22 + 23 Set a Post From old B.T.

Laurel Rotted & Fir down Marked Visible.

Mark New B.T. { 16" Fir N 71 1/2° E 33 ft. Marked 1/4 S, C.S, B.T.
30" " S 18 1/2° W 27 " " " " " " }

Sec Cor 22-23 -26-27 Set Post. From Old B.T.
in good shape except Tree in S.E. Quadrant
Down.

Marked New B.T. 30 Fir S 13° E 24 1/2 Feet, 527 C.S, B.T.

Sept 23, 1940

1/4 Cor E. Bdy of Section 1,
Set this corner from original Fir B.T. (10") which is N 68° E
8 links. The other 8" chinquapin S 65° W 4 links is entirely
destroyed. Set 4"x4" chinquapin post + marked a new 24" Fir
B.T. N 48° W 12 ft, marked 1/4 S 1, T 32 S R 4 W, C.S, B.T.