

29-7

N. 1/4 Cor. Sec. 2 T. 29 S. R. 7 W.

Orig. Cor. Lost or obliterated

Set Cor. midway between N.E. Cor. 2 & NW. Cor. 2

Drove 4x4 Post, from which

A W. Fir 12" bears N. 35° E. 2.5 Ft.

#22: " " 15" " S. 45° E. 12.0 Ft.

A. Boyer D.C.S.
Oct. 15-1941
Wit.
Geo. Ollivant
Wm Ollivant

✓

stein Co Sur

July 30/1938

10024700

cont. on
194

29 - 7

H. Eppstein Co Sur
Harold Bellows
N. E. Richardson
Ware

#23

✓ Most South-easterly or SE Ext. "L" Cor To D.L.C. No 38
✓ A square Carved Rock 12" x 12", 12" above ground in place for corner B.T. same.
Marked New Bearing Tree 20' W. O. Bearing 561W. 84.9 ft.
Marked C138 C.S. B.T.

#24
June 7, 1937.

✓ SW Cor of C138. Set 1" x 30" Iron Pipe for Corner from the old Pine Bearing Tree. Other Tree gone
Marked A 16" White Oak Bearing 513°W 71.0 ft.
Marked C138. C.S. B.T.

#25

✓ Most Southerly or South Ext. "L" Corner of D.L.C. 38. set in from a white oak stump, bearing N40E 134.1 ks. Showed sign of old Blaze in wood no scribe marks
Set 1" x 24" Iron Pipe for corner, from which 10" White Oak Bear N75°-45' W. 14.4 ft
Marked C138 C.S. B.T.

#25

✓ Int. "L" Cor of D.L.C. No 38
This Cor was set from bearing & distance from the Ext. "L" Cors, both East & South. No original witness trees
Set 1" x 30" Iron Pipe for corner, from which 14" White Oak Bears S. 74°E 158.4 ft.
Marked C138. C.S. B.T.
#

#27

✓ N.E. Cor of Sec. 27 Corners as recorded in the Govt. field Notes. in place except that the tree to the N.W. has been destroyed. Blazed & scribed a Fir 8" diam which brs N29°W 93.1 ks T29SR7W S27 CSBT.
#

#28

✓ Corner between secs, 26 & 26 1/2 on South Boundary of sec 23 - A rock as described in the Govt field Notes. One bearing tree has been destroyed by fire. The other is downrotting
Marked new B.T.

cedar 8" diam bears S15°W 25 lbs blazed & scribed T.29S. R.7W. S26 1/2, C.S. B.T.

Fir 8" dia bears ^{20°} ~~S~~ E 22 lbs blazed & scribed T.29S. R.7W. S26; C.S. B.T.

July 30, 1938
Ben B Irving
wit N.E. Richardson