

T30S R3W

V16-E55
Ben B Irving DCS.
Wit
N.E. Richardson
Loren Weber

Sec Cor 27-28-33-34.

Oct 9 1940.
All bearing trees have been destroyed a stump checks S W
for a possible B.T. Mr W. T Wright state that a rock chise marked
was along side a Yew wood gate post for many years.
after he acquired the property around this corner. The
location checks with distances to road & river as recorded
In accordance with this evidence, drove a truck axle 1 1/4" diam.
flush with ground for Corner. No trees convenient so
scribed Yew Wood Gate Post along side Corner
COR. 27-28-33-34 C.S.

T33 No

1/4 Cor. on North side Section 5. T.33S.R.6W.

1/2" Eye bolt already set in ground.

found stump of original B.T. S.25°E. 69 ft.
no trees available.

J.J. Wendert
M.E. Richardson
April 1942

1/4