

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 1 E. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

23

1/4 Corner to Sections 30 and 31.  
Found - 1927 GLO Brass Cap properly marked, but far around. #52  
Reset - in proper position from the following BT's:  
Orig. 18" now 16" Fir, alive, S 48° W. 23.8 ft., shows good  
scar. We do not open.  
Orig. 10" now 16" Hemlock sawed Stump, N. 10 1/2° W. 33.0 ft., shows  
"BT" scribe on unhealed blaze.  
New BT: 6" Chinq. N. 26° E. 68.7 ft. mkd. 1/4 S31 CS BT.  
Note - Corner lies on N. edge of Cat. fire trail on S. edge of logged unit.

1/4 Corner to Section 31 only, T25-1E. 24  
Found - 1927 US GLO Brass Cap properly marked & BT's. as follows:  
8", now 9" Fir Stump, N. 25° E. 63.4 ft., shows "BT" scribe on  
unhealed blaze.  
6", now 9" Fir, Alive, N. 75° W. 13.9 ft., shows good scar. Don't opn.  
New BT: 7" D.Fir N. 58° E. 16.9 ft. mkd. 1/4 S31 CS BT.  
Note - This corner lies 100 ft. N. of Canton Creek Access Road.

MICROFILM TO HERE -10/67

25

Corner #1 Mineral Survey # 501  
Found: Rotted Remains of 4" square wood post, no marks remaining, near a small  
mound of stone.  
From which: An orig 40" fir, now an 8 ft tall rotten snag bears north 6.0ft.,  
with scribing "BT" visible on wood fragments.  
An orig. 18" now 24" D.Fir bears S 7 1/2° W., 21.0ft., alive and well-healed.  
At the corner point, we set a 1"x30" I. pipe 10" in the ground to the bedrock  
and supported in a mound of rock 3 ft. at the base and 1 ft. high, with  
Brass cap attached, Mkd: T 25 S R1E  
DOUGLAS CO. SURVEYOR  
1975  
M.S.  
Cor. 1 501  
Note: This nonument is set leaning to the west.  
We mark a new bearing tree:  
A 14" D.Fir bears N 20° W., 15.4ft., scribed "1 MS 501 CS BT" on a double blaze.  
Note: This corner lies approx 40 ft. west of Steamboat Creek. Magnetic  
Declination : 20° E. 9/10/75

Corner #2 Mineral Survey #501 26  
Found: Orig 24" now 34" D.Fir, alive and well-healed, bears N 40° E., 24.0ft.  
A Down and rotten ceder bears N31 1/2° W., 25.5ft., with illegible reverse  
scribe marks visible on healed wood.  
At the corner point, we set a 1"x30" I. pipe, with brass cap attached. MKD  
DOUGLAS CO SURVEYOR T25S R1E  
1975  
Cor. 2 M.S. 501  
We mark the following bearing tree for this cor.  
A 7" Grand Fir bears S22° E., 3.4 ft., scribed: "2 MS 501 CS BT" on a double  
blaze. Dompass Declination setting: 20° East  
9/8/75

Corner #3 Mineral Survey #501 27  
Found: No remains of original corner. Corner and accessories destroyed by  
camp ground construction.  
New: We set a 5/8" iron rod at the corner as it falls in the road.  
An 11" maple scribed "3 MS 501 CS BT" in a double blaze bears S 50° E.,  
69.0 ft.  
A 16" Fir scribed "3 MS 501 CSBT" in a double blaze bears N72 1/2° E., 71.6ft.  
Compass Declination 20° East. 9/29/75

Vernon "Ray" Tracy  
Jack Heritage & D. Wast  
March & April, 1967  
C.S. File No. 52/30

Sept. 68

Clell Goodwin  
Vic Cangie  
Lenora Ladig  
CS 57/30  
9/29/75 M 58-23