

Douglas County Surveyor's Record of
Government Corners Renewed

E

T 25 T. S. R 1 E R.W/W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

37

1/4 Corner for Sec. 2 only. (North)

Found - 1" Iron pipe with a 1928 GLO brass cap attached properly marked.
Pipe is set loosely in ground.

From which - A 12" Douglas fir bears S.26°W., 14.52 ft. Has a single healed blaze.

A 17" Douglas fir bears S.45°E., 25.08 ft. This tree is still living but all signs of a blaze have been destroyed by logging activities.

Set - I place a mound of stone around the iron pipe.

New BT - An 18" Douglas fir bears S.70°30'E., 35.4 ft. scribed "1/4 S2 BT" on double blazes.

Note - Corner 1/4 S35 T24S, R1E, bears East, 65.97 ft. (Rec. N.88°14' 96 lks. or 63.36 ft.) U.S.F.S. bearing tree signs were placed on all BT's. This corner is about 50 ft. north of F.S. Rd. #2512.

1/4 Corner for Sec. 35 only for T24-1E.

Found - Orig. corner stone, which measures 20" x 14" x 5", is loosely set in the ground and is broken in half. Stone is marked "1/4 35".

From which:

A 30" Douglas Fir stump bears S.45°30'E., 29.7 ft. with a chopped out blaze as per 1928 record.

A down and decayed madrone, whose stump bears N.33°E., 11.88 ft. No marks visible.

A 14" Douglas fir stump bears N.44°W., (not 44"E.) 25.9 ft. and 27.72 ft. slope distance. I open snag lying alongside this stump and find scribing "1/4 S35 BT".

Set - Moving the corner stone aside, I set in its place a 1 1/2" x 5" iron pipe with a 2 1/2" brass cap attached marked:

T24S R1E 1/4 S35 P.L.S. 1636 1979

I bury corner stone alongside.

From which:

A 26" Douglas fir bears N.54°W., 70.2 ft. scribed "1/4 S35 BT" on double blazes.

A 19" Douglas fir bears N.24°E., 27.2 ft. scribed "1/4 S35 BT" on double blazes.

Note: Compass declination: 18°E. Corner 1/4 S2, T25S R1E., bears west, 65.97 ft. (Rec. S.88°14'W., 96 lks or 63.36 ft.) U.S.F.S. bearing tree signs were placed on all BT's. Corner is about 50 ft. north of F.S. road No. 2512.

4/19/79

Section corner for Secs. 35 and 36 only of T.24-1E.

Found - Original corner stone was found loosely set in the ground. The stone, which measures 14" x 9" x 5" is marked with 5 grooves on the west face and one groove on the east face. No other marks discernible.

A 38" D. Fir bears N.23°30'W., 72.6 ft. & has a nearly healed single blaze which has been previously opened.

A 24" D. Fir bears N.74°E., 107.58 ft. & has a healed single blaze. This tree has been badly damaged by rockfall.

Nothing remains of the other bearing trees of record.

Set - Moving the corner stone aside, I set in its place a 1 1/2" x 6" iron pipe with a 2 1/2" brass cap attached marked: T24S R1E S35 S36 S1 T25S R1E P.L.S. 1636 1979.

New BT - A 15" D. Fir bears N.25°30'W., 56.8 ft. scribed "24S R1E S36" on a double blaze.

Note: Compass declination: 18°E. Corner S1 S2 (T25S-R1E) bears S.80°30' W) 57.3 ft. (Rec. S.89°02'W., 0.86 ds.)

Corner lies approx. 75 ft. north of F.S. Rd. No. 2512. U.S.F.S. bearing tree signs were placed on all BT's.

4/26/79

Dennis Gaylord, L.S. 1636

U.S.F.S.

April 19, 1979

C.S. 60/24

(Set Stone Alongside)

38

36

39