

Douglas County Surveyor's Record of  
Government Corners Renewed

26

T. S.

2

E.

R. W. W. M.

*BEN IEWING*  
Wit.  
Les Kerchner ch.  
Elmer Wright exe  
July 24, 1945.

*C.S. FILE 38/31 N12-40*

H.E.S. # 178 CORNER # 3.  
Pine B.T. gone. Found corner as recorded in the official  
Government Field Notes. Blazed  
A 10" Fir N.17 $\frac{1}{2}$ °W., 15.4 ft. Cor. No. 3 H.E.S. 178  
C.S.B.T.

1

H.E.S. # 178 CORNER # 4.  
Found Rock displaced. Replaced in original location  
from both original B.T.s. Drove 5/8" x 24" Iron Rod  
alongside, top flush with ground.

2

H. E. S. No. 227, Corner No. 3.  
Found - 18" x 12" Stone at Corner chisled HES 227, from which  
23" Fir bears S.79°W. 21.5 ft., shows good scar.  
31" Fir bears N. 5°E. 24.2 ft., shows good scar.  
I open S. W. BT. & find good scribing 3 HES 227.  
Note - Corner is located in about center of roadway now under  
construction. I set Wit. Cor. 40 ft. East of true corner.  
Set Brass Cap at Wit. Cor. Mkd: County Surveyor's Office, 1960  
Wit. Cor. 40' West to 3 HES 227 T26S R2E.  
New BT's: 12" Cedar bears S. 7°E. 23.7 ft. scribed 3 HES 227 CS BT.  
9" R.Fir bears N.41 $\frac{1}{2}$ °E. 32.8 ft. scribed 3 HES 227 CS BT.

3

H. E. S. No. 142, Corner No. 5.  
Found - Orig. 15", now 24" Fir Stump N.74°20'E. 23.1 ft. We open  
& find good scribing "142 BT"  
Orig. 10", now 24" Fir checks bearing & distance for NW. BT.  
Corner at East edge of Roadway - Corner Stone not found.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
Corner No. 5 HES 142 T26S R2E  
New BT's: 8" R.Fir bears N.20°E. 30.8 ft. scribed 5 HES 142 CS BT.  
10" R.Fir bears S.77 $\frac{1}{2}$ °W. 21.4 ft. scribed 5 HES 142 CS BT.

4

*Oct. 1969 - FOUND BOTH CORNERS. O.K. C.S. 52/43 V.R.T.*

Corner No. 1 - H. E. S. No. 142,  
D. Fir sawed Stump 36" diam., from which the Orig. BT's:  
A cedar sawed stump 18" bears N.64°W. 67 lks. dist. with bottom  
part of axe face.  
A Douglas Fir sawed stump 30" bears N.12°E. 96 lks. with bottom part  
of axe face.  
New BT's: 8" Cedar bears N.12°E. 49 lks. mkd. 1 HES 142RS404 BT  
10" Cedar bears S.60°E. 88 lks. mkd. 1 HES 142RS404 BT.

5

Corner No. 1 - H. E. S. 227.  
Orig. BT's: D. Fir sawed stump 50" bears S. 5°E. 42 lks. with bottom  
part of axe face.  
D. Fir sawed stump 26" bears N.57°E. 102 lks. with bottom  
part of axe face.  
Set an I. P. 3' long 1 $\frac{1}{2}$ " diam 28" in gr. mkd: RS404 from which:  
18" D.Fir bears N.37°E. 47 lks. mkd: 1 HES 227 RS404 BT.  
16" D.Fir bears N.67°W. 59 lks. mkd; 1 HES 227 RS404 BT.

6

Corner No. 4 - H. E. S. 227.  
Orig. BT's: 38" S.Pine stump bears S. 87°E. 29 lks. mkd. 227 BT  
44" D.Fir stump bears S. 38°W. 96 lks. mkd. 227 BT.  
Set an I. P. 3' long 1 $\frac{1}{2}$ " diam 28" in the gr. mkd. RS404, from which new BT's:  
28" D. Fir bears N.68°E. 39 lks. mkd. 4 HES 227 RS404 BT.  
16" D. Fir bears S.27°W. 86 lks. mkd. 4 HES 227 RS404 BT.

7

Corner Common to 2 HES 142 & 2 HES 227 .  
This is a D. Fir 32" with marks healed, from which Orig. BT's:  
30" Y. Pine Stump bears S.17 $\frac{1}{2}$ °W. 45 lks. mkd. HES 227 BT.  
30" D.Fir bears West 76 lks., down with marks burned out.  
New BT's: 14" D.Fir bears N.20°W. 45 lks. mkd. 2 HES 142 RS404 BT.  
16" D.Fir bears S.14°E. 73 lks. mkd. 2 HES 227 RS404 BT.

8

JAMES W. BYRON, Deputy  
MILLO GODFREY  
CLETE PUTNAM  
August 6, 1960  
C.S. File No. 52/43

MARVIN C. RAMSEY  
Done for: J. H. Baxter & Co.  
Assistants: J. Goodin & R. Schultz  
September 12 - 22, 1960  
C. S. File No. 51/126

*RE-RENEWED. SEE CORNER NO. 29*  
*RE-RENEWED. SEE CORNER NO. 30*  
*RE-RENEWED. SEE CORNER NO. 51*  
*RE-RENEWED. SEE CORNER NO. 53*  
*RE-RENEWED. SEE CORNER NO. 22*  
*RE-RENEWED. SEE CORNER NO. 37*  
*RE-RENEWED. SEE CORNER NO. 50*  
*RE-RENEWED. SEE CORNER NO. 23*