

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 26 S. T. S. R. 2 E. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

16

Vernon "Ray" Tracy  
J. Heritage-V. Perron-J. Powell  
Feb. 13, 1968  
C. S. File No. 52/43

Witness Corner to  $\frac{1}{4}$  Cor. Secs. 26 & 35.  
Found - 1929 GLO Brass Cap in good condition, properly marked.  
Orig. 12", now 15" Fir, alive, S. 54° W. 44.9 ft., shows good scar,  
We do not open. This tree falls inside of R/W for new road.  
Orig. 10", now 12" Cedar, alive, N. 74° W. 52.1 ft., scribe marks  
visible on partially healed blaze.  
Move Brass Cap 40 ft. north of true corner point and Reset, Add Mks.:  
"Wit. Cor. 40 ft. S. to Cor." & drive 5/8" I.P. at true  
corner point.  
New BT's: 13" W. Fir S. 67° E. 9.0 ft. mkd. W.C.  $\frac{1}{4}$  S35 CS BT.  
15" W. Fir N. 40° E. 6.8 ft. mkd. W.C.  $\frac{1}{4}$  S26 CS BT.  
Note - Wit. Corner lies on top of ridge, course E. & W.  
True Corner lies on N. edge of R/W. - 100' N. of new road, as constructd  
Orig. 12" Cedar bears S. 64° W. 56.9 ft. from Witness Corner.

Richard C.  
Grant  
8/1966  
C.S. File  
No. 55/71

$\frac{1}{4}$  Corner to Sections 5 and 6.  
Found - 1930 GLO Brass Cap, pipe buried 6" below surface on  
edge of gravel.  
Note - Road destroyed old bearing trees.  
New Bearing Trees: 50" D. Fir S. 85° W. 40.3 ft., mkd:  
mkd: " $\frac{1}{4}$  Cor. S 6 T26S R2E 2807".  
48" D. Fir N. 76° E. 51.7 ft., mkd:  
mkd: " $\frac{1}{4}$  Cor. S5 T26S R2E 2807".

17

Sept. 68

August, 1966

Corner No. 3, of H. E. S. #93.  
Found - Corner Stone as called for, buried in old fill for driveway  
which is very seldom used, See Ren. #14.  
16", now 17" D. Fir, alive, S. 2° E. 5.9 ft., scribe visible, we tag.  
12", now 14" D. Fir, alive, N. 13° E. 27.1 ft. scribe visible, we tag.  
Set - Brass Cap at S.W. end of Stone, flush with road surface mkd:  
County Surveyor's Office, 1969 T 26 S R 2 E  
Cor. #3 HES 93  
The S. E. Corner of cabin bears N. 34 $\frac{1}{2}$ ° W. 36.3 ft.

17A

11/3/69

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
November, 1969 C.S. File No. 52/43

Corner No. 5 of H. E. S. #93.  
Found - Corner Stone, in place, as called for, Mkd: "5 HES 93 on side  
facing claim.  
Orig. 36", now 48" D. Fir, alive, N. 66 $\frac{1}{2}$ ° E. 115.5 ft., prev. opened  
with scribe marks visible.  
Set - Brass Cap at Cor. in place of Corner Stone, Reset Corner Stone Alngsd.  
County Surveyor's Office, 1969 T 26 S R 2 E  
Cor. #5 HES 93  
New BT's: 28" D. Fir N. 69° W. 46.6 ft. mkd: "5 HES 93 CS BT".  
6" W. Oak S. 26° W. 7.4 ft. mkd: "5 HES 93 CS BT".  
This corner lies on very steep, S.W. slope about 100' W. of top of  
spur, ridge sloping S.E.

18

11/4/69

Corner No. 6 of H. E. S. #93.  
Found - Corner Stone, as called for, in place, mkd: "X" on top &  
"6 HES 93" on side facing claim.  
Orig. 18", now 22" Oak, alive, N. 61° 20' W. 49.5 ft. (Rec. 39.6') Open  
& find "6" reverse scribe, blaze faces corner stone.  
Orig. 15", now 24" Fir, now stump, S. 54° 15' W. 68.0 ft. (Rec. 36.3')  
Open & find "6HE" scribe & reverse, blaze faces corner stone.  
We assume Orig. Dist. to be in error & accept Orig. Bearings.  
Set - Brass Cap in place of old corner Stone mkd:  
County Surveyor's Office, 1969 T 26 S R 2 E  
Cor. #6 HES 93  
New BT's: 8" W. Oak N. 36° W. 25.3 ft. mkd: "6 HES 93 CS BT".  
12" Pine N. 77° W. 33.0 ft. mkd: "6 HES 93 CS BT".  
This corner lies on steep, S.W. slope.

19

11/5/69