

Douglas County Surveyor's Record of
Government Corners Renewed

T 26

T. S.

2 E

E
R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

Robert Dean L.S. #1808
For: U. S. Forest Service
December, 1984
M 98 - 16 and C.S. 63/5

Robert Dean
LS #1808
For: U.S.F.S.
Jan. 18, 1985
M 98 - 20
C.S. 63/5

Robert G. Dean
LS #1808
For: U.S.F.S.
Jan. 25, 1985
M 98- 27
C.S. 63/5

56

Corner #4, H.E.S. #229
Found - 46" D. fir, healed scar per HES 229, from which
A 1" galv. I.P. with 2 1/2" brass cap bears N.7°00'E., 4.20 ft.
(Rec. North 4.0 ft. per Ren. #41).
I ADD - figures " RM LS 1808" to the cap.
Found - 36" sawed D. fir stump, no marks, bears N.39°15'W., 113.0 ft.
(Rec. N.39°15'W., 110.22 ft. per HES 229)
13" D. fir, healed scar, bears N.8°30'W., 81.7 ft. (Rec.
N.6°W., 82.1 ft. per Ren. #41)
40" D. fir healed scar, bears S.85°00'E., 15.0 ft. (Rec.
S.85°30'E., 13.86 ft. per HES 229)
9" D. fir, healed scar, bears S.83°30'W., 31.9 ft. (Rec.
S.85°W., 32.3 ft. per Ren. #41)

57

Corner #6, H.E.S. #229
Found - 21" D. fir per HES 229, "S2" visible, from which
a 1" galv. I.P. with 2 1/2" brass cap per Ren. #43, bears
N.62°00'E., 1.70 ft. (Rec. N.60°E., 2.0 ft. per Ren. #43)
I ADD - figures " RM LS 1808" to the cap.
Found - 23" D. fir, healed scar, bears N.41°20'W., 10.7 ft. (Record,
N.42°15'W., 9.24 ft. HES 229)
23" D. fir, healed scar, bears N.88°45'E., 10.0 ft. (Record
N.85°45'E., 8.58 ft. HES 229)

58

1/4 Corner for Sections 23 and 26
Found - 3/4" galv. I.P. with 2 1/2" brass cap, 1929 GLO cap properly mkd.
A pine stump hole bears N.16°40'E., 40.8 ft. (Rec. N.18°E.,
40.26 ft. per GLO.)
New BTs - 15" D. fir scribed "1/4 S26 BT" bears S.18°38'E., 184.6 ft.
15" W. fir scribed "X BT" bears S.71°00'E., 248.5 ft.
A 3/4" brass disc stamped "RLS 1808" is nailed low to the face of each
new BT.

12/30/84

59

Corner #2, H.E.S. #178
Obliterated corner restored in original location according to:
1: Testimony of property owner Mr. John Aymond, who remembers that the
drill steel mentioned in C.S. M12-40 used to lie under a fence which
ran north/south on the west side of the old road. He showed me the
stumps of the old fence posts sawed off at ground level.
2: The record bearing and distance from the stump of a bearing tree of
the 1913 Listing Survey. (copy of Listing Survey filed in C.S.63/5)
Set - 2" x 30" magnetic alum. monument in 36" cairn, marked "T26S R2E
2 HES 178 LS 1808 1985".
From which: SEE LISTING SURVEY NO. #74
1" x 29" bent drill steel per M 12-40, lying loosely, pointed in
north/south direction, covered by 1 inch of soil and turf, bears
N.85°W., 0.2 ft. from corner location. The drill steel is now
placed inside the new monument.
60" ponderosa pine sawed stump, no marks, bears S.2°15'E., 402.6 ft.
(Rec. S.2°15'E., 402.6 ft. per Listing Survey)
New BTs-11" W. oak, scribed "2HES178BT" bears N.49°45'E., 311.7 ft.
17" D. fir, scribed "2HES178BT" bears S.13°00'E., 374.8 ft.
A 3/4" brass disc stamped "RLS 1808" is nailed low to the face of
each new BT.

1/18/85

60

Corner #1, H.E.S. #93
Found - Corner location by intersection of distances from original
BT stumps.
Set - 2" x 30" magnetic alum. monument, marked LS 1808 1 HES 93
1985". T26S
R2E
From which:
1 1/4" x 32" galv. iron pipe per Ren. #11 with 3/4" brass disc
stamped "RS 404" inside, lying loose N.65°42'W., 1.08 ft. I
place this pipe inside the new monument.
20" ponderosa pine, healed scar, N.6°35'E., 88.3 ft. (Rec.
N.7 1/2°E., 87.78 ft. per ren. #11.)