

Douglas County Surveyor's Record of
Government Corners Renewed

T 28 T. S. 1 E R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner for Sec. 36 and Sec. 1, T29-1E
Found - 1" Iron pipe with brass cap attached, bent over but
still firm in the ground, marked U.S. General Land
Office Survey 1/4 S36 S1 1921

from which:

An orig. 42" now 30" Incense Cedar bears N.23° E., 20.5ft
alive and well healed.

An orig. 14" now 12" D.Fir bears S.2° E., 6.6 ft. alive
and well healed.

We remove the brass cap, straighten it and reset it "inches in
the ground at its present position.

This corner lies on a south slope, approx. 100 ft. north of
U.S. Forest Service Road No. 284 and approx 500 ft. east of the
concrete bridge crossing over Quartz Creek on Road No. 284.

7/1/74

1/4 Corner for Sec. 34 and Sec. 3 of T29-1E

Found - Iron pipe, firmly set, protruding 6" above ground
level with brass cap attached mkd: U.S. General Land
Office Survey 1/4 S34 S3 1921.

from which:

An orig. 16" now 20" D.Fir bears N.81°W., 15.2 ft.
well healed.

A stump hole with fragments of madrone roots bears
S.31°W., 5.9 ft, the remainder of the tree is gone.

New BT - A 22" D.Fir bears S.5°W., 26.3 ft. scribed "1/4 S3 CS BT"

This corner lies approx 75 ft. west of and 30 ft. below an
all-weather logging road.

7/22/74

1/4 Cor. for Sec. 35 and Sec. 2 of T29-1E.

Found - 1" I.P. with 1921 U.S. GLO brass cap properly mkd.

leaning & loosely supported in a mound of rocks. Due
to inconsistencies found in the measurements from the
brass cap at its present location and the fact that the
mound of rocks is not mentioned in the orig. field note
we remove the brass cap and reset it at the following
measurements from the remains of the two orig. BT's:

An orig. 30" now 36" Fir snag bears N.4°E., 16.5 ft.,
we open and find good scribing "5" on a rotten face.

An orig. 7" now 9" Madrone bears N.83°E., 7.3 ft.

(rec. S.83°E., 7.3 ft.) We find some illegible scribe
marks on an open blaze that has been deface some years
earlier.

The brass cap is now set 16" in the ground to solid rock and sup-
ported by a mound of stone 2 ft. wide by 1 ft. high, from which
we mark the following:

New BT's - A 14" D.Fir bears N.50°W., 28.2 ft. scribed "1/4 S35
CS BT.

A 9" D.Fir bears S.13 1/2°W., 27.0 ft. scribed "1/4
S2 CS BT"

7/29/74

Section Corner for Secs. 32 & 33; and Secs. 5 & 4 T29-1E.

Found - 1921 U.S. GLO brass cap properly mkd.

From which:

An orig. 14" now 24" D.Fir, bears N.85°E., 33.4 ft.
(rec. N.85°E., 32.3 ft.) alive and well-healed.

Note: The orig. distance is correct if taken to the
face of the tree.

An orig. 48" now 52" Incense Cedar, bears S.85°E.,
19.1 ft. alive and well-healed.

An orig. 40" Fir, now a windfall bears S.77°W., 86.5 ft.
Base of tree covered by dirt.

An orig. 48" now 52" Incense Cedar, bears N.31°W., 55.4'
alive and well-healed.

New BT - A 9" D.Fir, bears S.28°W., 23.8 ft. scribed "T29S
R1E S5 CS BT".

8/12/74

Gary Langlitz
Peter Earle
C.S. 57/2
July 1, 1974
July

Gary Langlitz
Peter Earle
C.S. 57/2
July 22, 1974

Gary Langlitz, County Surveyor's
Office
P. Earle
G. Commons
C.S. 57/2
July 1974

Gary Langlitz
Peter Earle
C.S. 57/2
August 1974

JAN 75
3-77

JAN 78
1-79