

Douglas County Surveyor's Record of
Government Corners Renewed

T. 19 T. S. R. 8 R. W. W. M.

KOKE-CHARMAN CO., EUGENE, ORE. 21881

South 1/4 Corner of T.19-7, Sec. 31
Found - 1949 Brass cap. ~~I T 19-7 & T 20-7~~
D. Fir stump 32", 4.6 ft. high, peeled, treated and covered with metal roff, tagged, bears N.30°W., 9 ft.
D. Fir stump 40"; 3 ft. High, pealed, treated, and covered with metal roof, bears N.30°W., 35.5 ft.
Corner is along cutting line, approx. 200 ft. south of road #20-7-5.3 line crossing tage on road near SW section corner.

Robert J. Walter for
U.S. Department of
the Interior
C.S. 58/11
Oct. 4, 1974

Section Corner for Secs. 29, 28, 32 and 33.
Found - 1952 U.S. GLO brass cap on I rod surrounded by mound of rocks.
An. orig. 18" Fir, S.51°E., 12.5ft. (rec. S.65 1/2°E.,) is now 42" stump capped.
An orig. 24" Fir, S.45°45'W., 23.1 ft. (rec. S.48°W.) is now 35" stump.
An orig. 30" Fir, N.84°15'W., 12.5 ft. (rec. N.73°W.) is now 47" stump capped.

6

Gary E. Commons
P. Earle
Surveyor's Office
2/25/75
C.S. 57/17

The bearings on these BT's agree with those of 1952 Dependant Resurvey.
Also found - A 17" Fir, S.14°W., 34.3 ft. Is now a capped stump. Scribings visible on top and bottom of scar but center is burned.
A 50" Fir, N.20°45'E., 50.8 ft. is now a hollow burnt stump tipped and sliding down hill.
This corner lies approx. 400 ft. south of log landing on steep west slope. We do not remonument.

2/25/75

1/4 Corner for Sections 7 and 18.
Set - 3/4" Iron rod from original bearing trees

7

Section Corner for Sections 7, 8, 18 and 17.
Set - 3/4" Iron rod from which:
A 12" Fir, bears N.68 3/4°W., 26.7 ft.
A 10" Fir, bears N.66°E., 17.1 ft.
A 19" Fir, bears S.37 1/2°E., 17.0 ft.
A 11" Fir, bears S.73 1/2°W., 9.4 ft.

8

RE-RENEWED, SEE CORNER NO. 33

1/4 Corner for Sections 7 and 8.
Found - An orig. bearing tree, a 44" Fir, bears N.66 1/2°W., 42 lks.
Set - 3/4" Iron rod from which:
A 49" Fir, bears N.61 3/4°E., 55.8 ft.

9

1/4 Corner for Sections 17 and 18.
Set - 3/4" Iron rod from which:
A 18" Fir, bears S.22 3/4°W., 28.0 ft.
A 26" Fir, bears S.24 1/2°E., 41.4 ft.

10

Center 1/4 Corner for section 18.
Set - 3/4" Iron rod from which:
A 26" Fir, bears N.36 1/2°W., 48.1 ft.
A 35" Fir, bears N.26 3/4°E., 41.0 ft.
A 15" Fir, bears S.77 1/4°E., 31.2 ft.

11

RE-RENEWED, SEE CORNER NO. #32

1/4 Corner for Sections 8 and 17.
Set - 3/4" Iron rod from whcih:
A 27" Maple bears N.31°W., 15.3 ft.
A 14" Cedar, bears S.47°W., 31.8 ft.

12

1/4 Corner for Sections 18 and 19
Set - 3/4" Iron rod from original bearing trees.

13

RE-RENEWED, SEE CORNER NO. #19

October, 1974

Survey by Eugene District
Bureau of Land Management
Transit and tape survey by: Wayne Tinglum, Mark
Lichtenthaler, Larry Smith & Michael Bilderback.
Completed October, 1974
M 57 - 31

10/12/74