

Douglas County Surveyor's Record of
Government Corners Renewed

T 19 T. S. R 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Thomas W. Ray, District Engineer
Oregon State Board of Forestry
Present & witnessed by D. O. Bryant
June 8, 1976
C.S 58/31

14

1/4 Corner common to Secs. 6 and 7.
Original: Post (now missing) from which a:
20" Fir, N.12°E., 25 lks.; now 28" Fir with face closed
& BLM tag affixed. (N.25°E., 16.5 ft.)
10" Fir, S.29°W., 19 lks.; now 10" snag with BLM tag
affixed, exposed scribing 4S (S15°W., 12.5 ft.)
Restored: Set 1 1/2" x 36" Galv. I.P. with brass cap mkd. "OREGON STATE
BOARD OF FORESTRY T19S R8W 1/4 S6 S7 1976 RS563", 6 inches
in ground, on 80% East aspect in mound of rock.
From which:
18" Fir, S.50°W., 8.9 ft. to face; scribed 1/4 S7 BT RS563.
No trees within limits in Sec. 6.
Set: 4"x4"x60" White painted Cedar post 4 ft. NE of corner pipe.
Oregon State Forestry Dept. metal location poster on 18" fir BT

15

Section corner to Secs. 5, 6, 7 and 8.
Original: Post (now missing) from which a:
18" Alder, N.14°E., 24 lks.; now 30" stump with tree rotted off
8" Maple, S.60°E., 38 lks.; now 21" with face open and
old axe work visible.
8" Alder, S.41°W., 43 lks.; now missing.
4" Vine maple, N.42°W., 50 lks.; now missing.
Stream 3 lks. wide, course East, bears South 6 chains (now
520 ft.)
Ridge West 7.25 chs., course East & West, with broad top
(now 700 ft.)
Restored: Set 1 1/2" x 36" Galv. I.P. with bronze cap mkd. "OREGON STATE BD.
OF FORESTRY T19S R8W S6 S7 S8 S5 1976 RS563" 6 ins. in ground,
in mound of rock,
From which:
20" Hemlock, S26°W., 63.9 ft. to face; scribed T19S R8W S7 BT
RS563.
20" Maple, N.19°W., 64.6 ft. to face; scribed T19S R8W S6 BT.
72" Fir, N.11°E., 75.6 ft. to face; scribed in bark T19S R8W S5 BT
No trees within limits in SE quadrant.
Set: 4"x4"x60" WPCP 5.0 ft. NW of corner pipe. Oreg. St. Forestry Dept.
metal location poster on orig. 8" Maple BT. Also poster on
30" Fir stump West 370 ft. on East side of Dun Ridge Road.
6/8/76

16

1/4 Corner for Sections 28 and 29.
Corner lost to mud and boulder slide. Corner proportioned by broken
boundary method:
Set - 5/8" x 20" re-bar in drill hole in boulder.
Set - 4-d spike in lead in drill hole N.34°W., 7.15 ft.
BT - 8" Fir, N.67°E., 21.1 ft. "W 1/4 S28 BT".

William Eimstad
For: Internat-
ional Paper Co.
April 1980
M 84 - 77

17

1/4 Corner for Sections 21 and 28.
Found - 15" Cedar, S.9°E., 33.0 ft. S and other marks.
20" Rotten maple stump, S.36°35'W., 23.76 ft. no marks remaining.
Re-set - 1952 GLO brass cap found buried in slide.
New BT - 9" Fir, S.13°W., 74.5 ft. "1/4 S28 BT".
Found - Iron rod, 0.92 ft. SW of corner.

Les Roberts LS# 1039
For: Intern. Paper Co.
March, 1982
M 91 - 73

18

Sec. corner to Secs. 18, 17, 19, & 20.
Found - 48" cedar snag bears N.66°W., 39.6-ft. (no marks)-1891 BT.
50" cedar bears S.87°W., 40.3-ft. (no marks)-1891 BT.
Set - 1-1/2" x 36" I.P. & Brass Cap
(4" x 4" x 36" squared post bears N.4°E., 6.0-ft.). 3/21/82
Note - Slope dist. used to re-set the corner.

19

1/4 corner to Secs. 18, & 19. Ren. # 13.
CONDITION REPORT ONLY
Found - 1980 BLM B.C., not of record.
BTs - 48" fir bears N.77°W., 24.1-ft. (scribe visible)-1891 BT.
62" fir bears S.77°E., 23.3-ft. (scribe visible)-1891 BT.
note - Survey M57-31 shows a 3/4" I.R. set. Fnd. no evidence of rod.
3/21/82