

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 19 T. S. R 8 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

Richard Hintz
For: International Paper Co.
M 103 - 6
Dec. 1986

30

1/4 Corner Sections 35 & 2, T 20-8.
Found - G.L.O. Iron Pipe 1" Diameter with brass cap 6" above ground.
BT's - 24" fir stump bears N 59°W, 33.9'. Marked "1/4 S 35 BT".
 21" fir stump bears N 67° E, 17.3'. Blaze rotted.
New BT's - 7" fir bears N 49 1/2°W, 43.7' to spike, Marked "1/4 S 35 BT"
 No other trees available.

1/4 Corner Sections 35 & 36.
Found - G.L.O. 1" diameter iron pipe with brass cap protruding
 10" above ground.
BT's - 48" fir bears N 6°W, 21.1', healed blaze.
 20" fir (down) bears S 63°E, 14.3' to center root hole.
New BT's - 23" fir bears N 40°E, 62.0' to spike, marked " 1/4 S 36 BT"

32

Center 1/4 Corner for Section 18
(Note: Corner referenced out Nov. 4, 1985. See C.S. 63/50 for reference notes.)

CONDITION REPORT

Found - 3/4" iron pin set by BLM in 1974 was destroyed by recent logging.
 Renewal No. 11
 16" fir, S. 77°E., 31.0 ft. (scar vis. 1974 BT. Rec. S. 77 1/4°E., 31.0
 28" fir stump, N. 36°W., 48.0 ft. (scar vis.) 1974 BT. Rec.
 N. 36 1/2°W., 48.1 ft.
 36" fir stump N. 28°E., 41.4 ft. (scar vis.) 1974 BT. Record
 N. 26 3/4°E., 41.0 ft.
 24" alder, S. 54°E., 8.80 ft. to R.R. spike in base RP set 11/4/85
 36" fir stump, N. 31°E., 39.60 ft. to R.R. spike in base.
 R.P. set 11/4/85.

Set - 2" x 36" aluminum pipe and cap using distances of 8.80 ft.
 and 39.60 ft. from R.R. spikes set on 11/4/85. Buried pipe
 magnetic marker under 36" pipe.

Set metal fence post, with survey attention sign wired to,
 beside aluminum pipe. Painted all BTs red.

No new accessories. Corner lies on N.E. slope about 150 ft. North of road.
 11/26/86

Section Corner for Secs. 7, 8, 18 and 17.

Found - 3/4" rebar. Ren. #8 *** 33**
 13" fir, N. 67°E., 17 ft. - closed face.
 23" fir, S. 36 1/2°E., 17.0 ft. - closed face
 14" fir, S. 73 1/2°W., 9.3 ft. - closed face.
 16" fir, N. 68 1/2°W., 26.9 ft. - closed face.

New Accessories:

20" fir, N. 35°W., 62.3 ft. scribed T19S R8W S7 BT.
Railroad spike in 16" fir stump, N. 83°E., 27.14 ft.
Railroad spike in 10" fir stump, S. 19°E., 26.73 ft.

Corner falls on southerly R/W of a proposed logging road and a new BT was
set to replace the BT in the road. This corner was also referenced
with RR spikes in stumps.

34

Southwest Cor. Sec. 31; Northwest Cor. Sec. 6 T20-8

Found - 3 1/2" Brass cap in good condition.
 30" Fir, bears S. 20°E., 57.1', healed face.
 51" Hemlock, bears S. 82 1/2°W., 24.3', healed face.
 46" Fir stump, bears N. 53 1/2°W., 49.4', no marks.
 31" Cedar, bears N. 3 3/4°E., 54.2', healed face.

New BT- 15" Hemlock, bears S. 84 1/2°E., 41.6', blazed & scribed
 "T20S R8W S6 BT"

Note - Corner lies on a North facing bench.

Les Roberts
L. S. #1039
November 26, 1986
C.S. 63/50

9/2/89
NOTE: All BTs now
stumps. Soaked tops
w/wood preservative &
covered w/0.020 thick alum.
24" Alder not treated
or covered)

Daniel Baker
L.S. 1978
May 13, 1988
C.S. 63/69

Wayne Donovan
L.S. #2553
CS File 63/153