

Douglas County Surveyor's Record of
Government Corners Renewed

T 19 T. S. R 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

Milo Godfrey
V. Tracey &
C. Putnam
For: U. S.
Plywood,
Mapleton
Nov. 9, 1961
C.S. File No.
52/94

Witness Corner for $\frac{1}{4}$ Corner to Sections 26 and 35.
Note - $\frac{1}{4}$ Corner is Brass Cap (GLO survey, 1958). Corner and Bearing Trees will be destroyed by road construction. #12
Set - Wit. Corner S.70°W. 130.0 ft. from true $\frac{1}{4}$ Corner.
Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961
T19S R9W W.C. $\frac{1}{4}$ S26" N.70°E.
S35" 130.0 ft.
Set - $\frac{3}{4}$ " Iron Rod S.70°W. 48.25 feet from Wit. Corner, thus:
S.70°W. 130 ft.
48.25' 130 ft.
New BT. $\frac{3}{4}$ " Rod Our Brass Cap GLO Cap
 $\frac{1}{4}$ Corner
New BT's; 43" D. Fir S.68°W. 48.3 ft. Mkd: W.C. $\frac{1}{4}$ S35 CS BT".
36" D. Fir N.70°W. 61.1 ft. Mkd: W.C. $\frac{1}{4}$ S26 CS BT.

1

RE-RENEWED, SEE COMPASS NO. #24-36

Mile E.
Godfrey &
Crew
C. S. File
No. 53/66

Corner to Sections 25 and 36, T19S R10W.
Found - 28" D. Fir, shows good scars.
40" D. Fir N.3 $\frac{1}{2}$ °W. 4.0 ft., shows good scars. FD. 3/27/80
38" Hemlock S.83°W. 46.9 ft., opened & found good reverse scribing. E. ALVARADO
W.S. FOR. 500V.
C.S. 6116
Set - Brass Cap at Base of Corner Tree (S.E. Side) & Mkd:
County Surveyor's T19S S 25 |
Office, 1964 R10W S 36 | R9W
Blaze & Rescribe: 40" D. Fir N.3 $\frac{1}{2}$ °W. 4.0 ft. Mkd: T19S R10 S25 CS BT.
38" Hemlock S.83°W. 46.9 ft. Mkd: T19S R10 S36 CS BT.
Sept. 29, 1964

2

RE-RENEWED

MICROFILM TO HERE -- 10/67

Vernon "Ray" Tracy
Jack Heritage & V. Perron
July, 1968
C. S. File No. 53/66

Closing Corner Sections 5 and 4, T20-9W.
Found - 1921 G.L.O. Brass Cap with badly rusted pipe, buried under
48" Cedar Log.
14" Maple, now 20" shattered stump, S.38°E. 17.8 ft., no
scribe found on unhealed blaze.
30"(?) Alder, now 24" Stump, S.15°W. 40.3 ft., blaze decayed, no scribe.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 19 S
(Deposit old corner Office CC S 5 | S 4
material alongside) 1968 T 20 S R 9 W
New BT: 30" Maple N. 12° W. 67.6 ft. mkd. "CC S4 S5 CS BT".
No other trees available.
Note - This corner lies 20 ft. E. of small ravine, course NE & 200'
south of middle fork of Smith River.
7/19/68

3

Sept '68

Vernon "Ray" Tracy
Jack Heritage & V. Perron
June 19, 1969
C. S. File No. 53/66

Section Corner to Sections, 32 and 33, T19-9W.
Found - 1921 G.L.O. Brass Cap, in place & firmly set.
Orig. 20", now 26" Fir sawed stump, N.83°W. 22.4 ft., shows scar.
No trace other BT due to slide.
There being no trees close, we set 5/8" I. Rod in front of
BT. stump N. 83° W. bearing 20.9 ft.
Set - 5/8" I.R. north 10.0 ft. and 6' steel fence post alongside Brass Cap.
This corner lies on very steep N. slope about 200' from log landing in Sec. 5.
7/19/68

4

Section Corner to Sections 4 & 3, T 19 S, 20S R 9W
Found - 1921 G.L.O. I.P. & Brass Cap Broken--No trace O.B.T.S. We
measure from Sec. Cor. 33 & 34 of T 19S R 9W to locate pipe. Record
Dist. is 335.3. We make it 332.0 Ft. on bearing of N. 86°E. β .86°W
at Cor. point in place of old pipe
Set - 1" I.P. & Brass Cap Mkd:
County Surveyors T 19S R 9W T 20S R 9W
Office, 1969 C. C.
S4/ S3
& Mk. new B.T.
48" D. Fir (stump) S. 27°E. 45.6 Ft. Mkd. CC S3 CS BT
No other trees or stumps available. This cor. lies on very steep
S. W. Slope 6-19-69

5