

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 19 T. S. R. 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner To Sections 33 & 34 Only

6

Found - 1921 G.L.O. Brass Cap on broken concrete filled I.P. in place.

30" Now 36" Fir N. 81°W. 23.8 Ft. Record N. 31°W. --Dead shows good scar. No trace of N.E. B.T. Fd.

T 19S S33/S34 R9W  
T 20S S4

At Cor. point in place of old pipe

Set - 1" I.P. & Brass Cap Mkd:

County Surveyors Office, 1969 T 19S S 33 / 34 T 20S R 9W

New B.T.

10" Maple N. 45°W 32.6 Ft. Mkd. T19S R9W S33 CS BT

No other trees close to N. E. This Cor. lies on very steep Southerly slope on E. W. Cutting line. Clear cut to South June 19, 1969

Vertical way Tracy  
Jack Heritage &  
6-19-69  
C. S. File No. 53/66

Center of Section 16.

Set - 5/8" Steel Rod

Scribed ----- 24" Fir N. 21° E. 45.3 feet  
25" Fir N. 38° W. 6.9 feet.

Nov. 1969

Wilford Haines  
11/69  
Map  
M 38 - 67

North 1/4 Corner to Sec. 4, T20-9W.

Corner established in 1921 by Collier.

Found cement filled pipe set in 1921 by GLO, from which:

40" Fir bears S.2°W. 12.4 ft., evidence of face.

Set - 2"x30" I.P. with brass cap mkd: T20S R9W

Set pipe alongside corner.

Set fence post with signs ± 5' S. facing E.

x  
4  
1970  
650

8

U.S. Forest Service  
Tom O. McCullough  
C.S. File No. 55/148  
April, 1970

1/4 Corner for Secs. 3 and 10.

Set - 2" x 36" Galv. I. Pipe directly under 18" rotted Fir tree which shows old marks for corner and is proper distances from bearing trees.

All bearing trees found.

NO BLM BRASS CAP FOUND.

4/75

9

S. Kendrick  
For: Davidso Ind.  
April, 1975  
M 57 - 9

1/4 Corner for Section 36, East 1/4 T19-10 only.

Found no evidence of the 1920 Government survey corner.

At proportional distance:

Set - 5/8" x 40" Iron rod

From which:

40" Red Cedar bears S.7°W., 87.2 ft. marked "BT 1/4 S36 T.19 S. R.10 W"

28" Red Cedar bears S.42 1/2°W., 58.8 ft. marked "BT 1/4 S36 T.19S. R.10 W"

6/3/78

10

JUN 27 6  
JAN 78

Forrest J. Hales  
For: International Paper Co.  
June 3, 1978  
M 71 - 62

Section corner for sec. 31 of T.19-9 and sec. 6 of T.20-9

Found - Remains of the 6" Chittem.

Set - 5/8" x 40" Iron rod S.20°W., 40 lks. from the uproot hole where the 6" Chittem stood.

New BT's-48" D. Fir bears N.32 1/2°E., 49.0 ft. marked "BT S31 T.19S. R.9W"

44" D. Fir bears S.53 1/2°E., 18.2 ft. marked BT S.6 T.20S R.9W.

6/3/78

11

1/4 Corner for Secs. 26 and 35.

Found - Witness Corner to 1/4 cor.; 1961 Douglas Co. Brass cap and 3/4" Rod, bears S.70°12'37"W., 48.75 ft. & 1/4 Corner N.70°12'37" E., 130.0 ft. See Ren. #1

Set - 5/8" x 24" Rebar in road for 1/4 Corner

Accessories: Concrete nail in lead in rock wall, N.80°W., 59.19 ft.

5/8" x 30" Rebar in rock seam, S.15°W., 41.92 ft.

5/78

12

Eimstad & Associates  
For: International Paper Company  
May 1978  
M 72 - 15