

Douglas County Surveyor's Record of
Government Corners Renewed

T. 19 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHARMAN CO., EUGENE, ORE. 21881

19

1/4 corner for Sec's 10, & 15.
Found - Brass Cap (BLM). 1968 - 1969 RESURVEY
BT's - 14" Fir bears S.23°E., 25.8-ft. (scar visible). 1968 BT
16" Fir bears N.02 1/2 °E., 17.1-ft. (scar visible). 1968 BT
7/16/81

Les Roberts
For: International Paper Co.
July 16, 1981
M 88 - 21

20

1/4 corner for Sec's. 9, & 10.
Found Brass Cap (BLM). 1968 - 1969 RESURVEY #42
BT's - 16" Fir bears S.46°W., 24.8-ft. (scar visible). 1968 BT.
18" Fir bears S.40°E., 7.8-ft. (scar visible). 1968 BT.
7/16/81

RE-RENEWED, SEE CORNER NO. #42

21

1/4 corner for Sec's.3, & 10. Renewal # 9.
Found - 2" Iron Pipe at base of 18" live Fir C.S. M 57 - 9.
Set - Brass Cap in the found I.P..
BT's - 30" Fir bears S.68°E., 11.3-ft. (scar visible). 1899 BT.
16" Fir bears S.54°E., 34.8-ft. (scar visible). 1957 BT.
18" Fir bears N.12°W., 19.5-ft. (scar visible). 1957 BT.
7/16/81

Ernesto Alvarado
U.S.F.S.
Witnesses: Colin Long
Carol Dickinson
March 12, 1982
C.S. 61/32

22

1/4 Corner for Sections 21 and 28
Found - 1969 BLM brass cap 7" above ground in good condition,
marked: S21 S28 1/4 T19S R9W 1969.
29" Hemlock bears N.45 1/2°W., 15.4 ft. scribing visible
1/4 S21.
SE BT has been destroyed by road construction.
New BT - 12" Hemlock bears S.9°W., 43.8 ft. marked "1/4 S28 CS BT".
Location - Go south on FS Rd. #23 approx. 0.7 miles past junction
with BLM Rd. #20-9.1 to Rd. #19-22.2. Then go to the end (turn right
at fork). Corner is 40 ft. west of the road. Location poster on east
side of road. Corner bears S.84°W., distance 77 ft.

3/12/82

23

Donald Peel LS #752
For: International
Paper Company
June 8, 1982
M 92 - 28

North 1/4 Corner Section 3 only of T.20-9
Found - 1921 US GLO brass cap lying beside rusted pipe.
Set - Drove 1 1/2" x 36" I. Pipe over top of original pipe and
cemented new cap in pipe. New cap marked "T20S R9W 1/4
S3 PLS 752 1982".
New BT's- 42" fir, S.64°E., 44.0 ft.
40" fir, S.8°W., 44.2 ft.

6/82

24

Ernesto R. Alvarado
S. Forest Service
Siuslaw District
Witness: Elwin Price
Sept 1982
C.S. 59/30

Section corner for Secs. 25 and 36 only of T.19-10
REFERENCED OUT DUE TO LOGGING IN AREA
Found - Corner tree, 28" D. fir uprooted.
Brass cap on root wad. Ren. #2
38" hemlock uprooted.
40" D. fir uprooted.
Set - At corner point - set 5 ft. steel post 1 1/2 ft. above ground
Brass cap placed alongside.
New Accessories:
38" hemlock to rootwad, bears N.87°W., 33.6 ft.
Uprooted hemlock, determined center of tree. At location
set 5 ft. steel post, bears S.82°W., 47.0 ft.
38" hemlock stump bears S.74°W., 47.3 ft. R.P. 8" x 3/8" nail.
Bearing and dist. to top of nail head.
36" hemlock stump bears S.41°W., 45.5 ft. R.P. 8" x 3/8" nail.
Bearing and dist. to top of nail head.
Referenced point: 43" hemlock snag bears N.71°E., 73.7 ft.
8" x 3/8" nail. Bearing and dist. to top of nail head.
Uprooted 28" D. fir bears N.2°E., 24.1 ft. (to rootwad).
Location: Go up F.S. Rd. #23 approx. 5.0 miles to location poster on North
side of road. From poster go north 10 chains to corner which
lies on North face.

RE-RENEWED, SEE CORNER NO. #36