

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 6 W. R. W. W. M.

KORF-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 27 - 28 - 33 - 34.

Found - $\frac{1}{2}$ " Rod, reinforcing rod, set by Hayden in 1950: ~~207~~ ³²
Old Fir Snag, outside rotted away, S.72°W. 13.2 ft.
Fir Snag, now 30", S.76°E. 13.9 ft. Hayden's
scribing "BT" visible in partially healed scar.
Fir Tree, now 10", South 17.6 ft. (Haydon & Haines BT.)
scribing visible in partially healed scar "BT".
I rescribe "T20S R6W S34 CS" above old scar.

Set - Alongside $\frac{1}{2}$ " Rod, Brass Cap Mkd: County Surveyor's
Office, 1962 T20S R6W

S28	S27
S33	S34

New BT's: 28" Fir S.77°W. 26.1 ft, Mkd: T20S R6W S33 CS BT.
22" Fir N. 3°E. 63.6 ft. Mkd: T20S R6W S27 CS BT (one blaze)
No other trees near.
No trace of any other Orig. or renewal BT's. found.

*FD-11/83
M 95-43
Lloyd Smith*

Section Corner to Secs. 24 & 25, T20-6W. & Secs. 19 & 30, T20-5W. ³³

Found - 12" Fir Snag S.65°E. 50.2 ft., scribing visible on old
face, previously opened, "T2 R5W S30".
Fir Tree, now 60", N.72°W. 17.8 ft., old bark scribing
visible, "T20S R6W S2".
I. Cedar, now 36", S.70°W. 27.7 ft., has been cut into
but ~~old~~ old face not exposed. These 3 trees still
in good condition. Distances noted to old face.

Set - I. Pipe with Brass Cap Mkd: County Surveyor's Office, 1962
^{Doug.}
T20S R6W

S24	S19
S25	S30

 R5W

Blaze & scribe one new Tree: 16" D. Fir S.60°E. 83.0 ft. Mkd:
T20S R5W S30 DCS BT.

Blaze & Rescribe 60" Fir N.72°W. 17.8 ft. T20S R6W S24 DCS BT.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy
Clete Putnam
January 1962
C. S. File No. 49/89

West $\frac{1}{4}$ Corner to Section 31. ³⁴

Found - Fir Tree, now 33", N.55°E. 13.2 ft., chopped open &
found good scribing "4 C". Ring count shows scribing
to be about 90 yrs. old. This proves it to be
McClung's corner set in 1872. Tree in good condition.
No trace found of N. W. Bearing Tree.

Set - Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1962.
T20S R6W $\frac{1}{4}$ S31

New BT: 20" Fir S.50°E. 35.5 ft. Mkd: " $\frac{1}{4}$ S31 CS BT".

West $\frac{1}{4}$ Corner to Section 19. ³⁵

Found - Fir, now 26"; N.5°W. 13.2 ft., chopped open & found
good scribing "4".

No trace found of S. E. B.T.

Set - Brass Cap at Cor. Mkd: Doug. Co. Surveyor's Office, 1962
T20S R6W $\frac{1}{4}$

S19
R7W
R6W

New BT: 26" D. Fir N.77°E. 14.8 ft. Mkd: " $\frac{1}{4}$ S19 DCS BT".
(On County Line - Doug. & Lane)

$\frac{1}{4}$ Corner to Sections 29 and 30. ³⁶

Found - Fir, now 14", N.80°W. (instead of N.70°W.) 8.6 ft. Tree
previously opened, scribing visible on old face " $\frac{1}{4}$ S".
Tree still alive and in good condition.

Fir Snag, now 19", S.12°E. 16.5 ft., chopped open & found
good scribing on old face. "S" & "BT" visible.

Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962
T20S R6W $\frac{1}{4}$ S30/S29

New BT: 17" D. Fir S.62°E. 31.0 ft. Mkd: " $\frac{1}{4}$ S29 CS BT".

Note: $\frac{1}{4}$ " Aluminum Pipe apparently set for this corner bears
S.23°W. 3.8 ft.

RE-RELEASED **RECORDED** **INDEXED** #65