

**Douglas County Surveyor's Record of  
Government Corners Renewed**

20 T. S. 6 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 91881

<p>David Wellman For: Weyerhaeuser Co. M120 - 55 July 1994</p>	<p>Section Corner for Sections 35 &amp; 36; Section 2 T21-6. <u>CONDITION REPORT ONLY; SEE RENEWAL # 22</u> Found - 2½" BLM Brass Cap dated 1984. 36" Fir, S.46½°E., 25.0 ft. - visible scribing rec. S.45°E., 38 lks. - 1872 GLO 32" Fir, N.72¼°W., 21.0 ft. - closed face, rec. unknown 18" Fir, N.68½°W., 12.0 ft. - closed face 19" Fir, N.52°E., 48.4 ft. - closed face rec. N.51°E., 75 lks. 1962 BLM. 20" Fir, N.53½°E., 45.0 ft. - closed face rec. N.54°E., 45.5 ft. - 1958 Douglas County 26" Fir stump, N.61½°E., 17.4 ft. rec. N.62°E., 26 lks. - 1984 BLM rec. N.65 ¾°E., 25 lks. - 1962 BLM rec. N.17½°E., 25 lks. - 1872 GLO</p>	<p align="right">70</p>
<p>Steven Ness for: Weyerhaeuser M 121 - 24 A&amp;B Oct. 14, 1994</p>	<p>See previous ren. #1 SE COR sec. 33 - Cond. report Monuments FD. - 2½" DCSO brass cap on 1½" I.P. Accessories FD. - 54" D.Fir, N.90°W. 38', large face partially opened no marks visible. (no rec.). 38" D.Fir, N.29½°W. 25', two large healed faces. (N.25°W 35').</p>	<p align="right">71</p>
<p>Les Roberts for: Seneca Timber M 123 - 60 April 1996</p>	<p>North ¼ corner section 26 (Amendedd) Mon. Fd.- 1962 BLM Iron pipe and Brass cap true corner, bears N.26°W. 7.05' (data from eugene BLM office) 18" Cedar, S.65°W., 53.7' (scar vis), 1962 B.T. 18" Fir, N.32°W., 37.1' (scar vis), 1962 B.T.</p>	<p align="right">072</p>
<p>Les Roberts For: Seneca Timber M 127=70 Nov. 1997</p>	<p>East 1/4 Corner Sec. 32 Fd. - "T" iron set by Haines in survey M 3-23 (Ren #12) 50" downed fir, N.1°W., 33.0', (No marks), 1872 BT Set - 6" Fir, S.7°W., 11.6' (scribed/metal washer/painted red) 6" Fir, S.71°E., 13.5' (scribed/metal washer/painted red)</p>	<p align="right">Fd OK Les Roberts 1-2000 M134-4 073</p>
<p>David Wellman Mar. 3, 1997 C.S. File 65/20-1</p>	<p>East 1/4 Corner Section 36 Found - Douglas County Brass Cap dated 1962 See renewal #29 BT's Found - 30" Fir stump w/tin cap, N.28°E., 20.0 ft. to spike set side center - closed face. 23" Hemlock, N.61°W., 17.4 ft. to spike set side center - closed face. 23" Hemlock, S.54°E., 17.6 ft. to spike set side center - closed face. (rec. N.54°E) New Accessories - 26" Hemlock, S.17½°W., 32.7 ft. to "W" nail - scribed "1/4 S36 BT"</p>	<p align="right">74</p>
<p>Dan Baker For: Weyerhaeuser Co. 3/10/1998 C.S. File 65/20-17</p>	<p>Corner for Sccs. 20, 21, 28, &amp; 29 Found - 1950 GLO brass cap (previous ren. #39) NE BT down and out of position. 21" Fir, S.34°E., 25.5 ft. - closed face, 1950 GLO New BOs - 17" Fir, N.83°E., 14.7 ft. to "W" nail - scribed "T20S R6W S21 BT" 9" Fir, S.57°W., 8.7 ft. to "W" nail - scribed "T20S R6W S29 BT" 12" Fir, N.33°W., 4.8 t. to "W" nail - scribed "T20S R6W S20 BT" 6 ft. Metal fence Post 1 ft. North.</p>	<p align="right">75</p>